




Linear Motor

User Manual

Revision History

The version of the manual is also indicated on the bottom of the front cover.

MP99UE01-2505_V1.5




Release Date	Version	Applicable Product	Revision Contents
May.2025	1.5	Linear motor	<ol style="list-style-type: none">1. Add LME series.2. Modify forcer parallel design of LMC-EFF, LMC-HUB, LME, LMSS.3. Supplementary stator warning and caution item.4. Supplementary the definition of stator polarity.5. Add note for pin of wiring diagram.
Dec.2023	1.4	Linear motor	<ol style="list-style-type: none">1. Force vs. air gap increased LMSA0 series in 3.2.1 section.2. Attraction force vs. air gap increased LMSA0 series in 3.2.1 section.3. Hall Sensor Revision Instructions for LMSA-Z series in 3.3.3section.4. Model explanation add label description in 1.3 chapter.5. Add stall conditions 2.1.2.4 section.6. Add assembly description of stamped stator of 4.1.1.1 and 4.1.1.2 section.
Apr.2023	1.3	Linear motor	<ol style="list-style-type: none">1. Increase extension cable installation instructions2. Increase voltage limit instructions
Oct, 2022	1.2	Linear motor	Typesetting revisions.
Mar, 2021	1.1	Linear motor	<ol style="list-style-type: none">1. Modify the flatness tolerance of motor assembly.2. Add the description of Hall's air gap.3. Add LMSA-Z series to the description of extension cable installation4. Add the selection of copper pillar for motor with connector.5. Correct the pin of signal.

Release Date	Version	Applicable Product	Revision Contents
May.2025	1.5	Linear motor	<ol style="list-style-type: none"> 1. Add LME series. 2. Modify forcer parallel design of LMC-EFF, LMC-HUB, LME, LMSS. 3. Supplementary stator warning and caution item. 4. Supplementary the definition of stator polarity. 5. Add note for pin of wiring diagram.
Dec.2023	1.4	Linear motor	<ol style="list-style-type: none"> 1. Force vs. air gap increased LMSA0 series in 3.2.1 section. 2. Attraction force vs. air gap increased LMSA0 series in 3.2.1 section. 3. Hall Sensor Revision Instructions for LMSA-Z series in 3.3.3section. 4. Model explanation add label description in 1.3 chapter. 5. Add stall conditions 2.1.2.4 section. 6. Add assembly description of stamped stator of 4.1.1.1 and 4.1.1.2 section.
Apr.2023	1.3	Linear motor	<ol style="list-style-type: none"> 1. Increase extension cable installation instructions 2. Increase voltage limit instructions
Oct, 2022	1.2	Linear motor	Typesetting revisions.
Oct, 2021	1.0	Linear motor	First edition.

Related Documents

The figure and table of the documents related to the product are shown below. Refer to these documents as required.



Product		Doc. Name	Doc. No.	Content
Controller	HIMC Motion Controller	HIMC Installation Guide	MH07UE01-□□□□	Provides detailed information on installing and connecting HIMC motion controller.
		HIMC iA Studio User Guide	MH01UE01-□□□□	Provides detailed information on the human machine interface operation of HIMC motion controller.
		HIMC Modbus TCP User Guide	MH02UE01-□□□□	Provides detailed information on the way Modbus TCP communication protocol applied to HIMC motion controller.
		HIMC HMPL User Guide	MH06UE01-□□□□	Provides detailed information on HMPL library of HIMC motion controller.
		HIMC API Reference Guide	MH05UE01-□□□□	Provides detailed information on API library of HIMC motion controller.
		HIOM Installation Guide	MH03UE01-□□□□	Provides detailed information on installing and connecting HIOM (HIWIN mega-ulink IO module).
		ETA3 Installation Guide	MH09UE01-□□□□	Provides detailed information on installing and connecting ETA3 (HIMC remote module).
Servo Drive	E Series Servo Drive	E1 Series Servo Drive User Manual	MD09UE01-□□□□	Provides detailed information on selecting, installing, connecting, setting, performing test run for, tuning, and monitoring E1 series servo drive.
		E1 Series Servo Drive Thunder Software Operation Manual	MD12UE01-□□□□	Provides detailed information on the human machine interface operation of E1 series servo drive.
		E1 Series Servo Drive EtherCAT(CoE) Communications Command Manual	MD08UE01-□□□□	Provides detailed information on the way EtherCAT communication protocol applied to E1 series servo drive.
		E1 Series Servo Drive MECHATROLINK-III Communication Command Manual	MD24UE01-□□□□	Provides detailed information on the way MECHATROLINK-III communication protocol applied to E1 series servo drive.
		E1 Series Servo Drive PROFINET Communication Command Manual	MD02UE01-□□□□	Provides detailed information on the way PROFINET communication protocol applied to E1 series servo drive.
		E1 Series Servo Drive Gantry Control System User Manual	MD22UE01-□□□□	Provides detailed information on the usage of E1 series servo drive gantry control system.
		E1 Series Servo Drive Electronic Cam Control System User Manual	MD27UE01-□□□□	Provides detailed information on the usage of E1 series servo drive electronic cam control system.
		MPI Library Reference Manual	MD19UE01-□□□□	Provides detailed information on MPI library of E1 series servo drive and D series servo drive.
		MPI Examples	MD18UE01-□□□□	Provides detailed information on MPI examples of E1 series servo drive and D series servo drive.
		API Library Reference Manual for Servo Drives	MD23UE01-□□□□	Provides detailed information on API library of E1 series servo drive and D series servo drive.
		PDL Examples for E1 Series Servo Drive	MD25UE01-□□□□	Provides detailed information on PDL examples of E1 series servo drive.
	D Series Servo Drive	D1 Servo Drive User Manual	MD20UE01-□□□□	Provides detailed information on selecting, installing, connecting, setting, performing test run for, tuning, and monitoring D1 servo drive.
		D2 Series Servo Drive User Manual	MD07UE01-□□□□	Provides detailed information on selecting, installing, connecting, setting, performing test run for, tuning, and monitoring D2T servo drive.

Product		Doc. Name	Doc. No.	Content
Servo Drive	D Series Servo Drive	D2T-LM Series Servo Drive User Manual	MD11UE01-□□□□	Provides detailed information on selecting, installing, connecting, setting, performing test run for, tuning, and monitoring D2T-LM servo drive.
		MPI Library Reference Manual	MD19UE01-□□□□	Provides detailed information on MPI library of E1 series servo drive and D series servo drive.
		MPI Examples	MD18UE01-□□□□	Provides detailed information on MPI examples of E1 series servo drive and D series servo drive.
		API Library Reference Manual for Servo Drives	MD23UE01-□□□□	Provides detailed information on API library of E1 series servo drive and D series servo drive.
		PDL Examples for D-series Drives User Manual	MD13UE01-□□□□	Provides detailed information on PDL examples of D series servo drive.
Motor	Linear Motor	Linear Motor User Manual	MP99UE01-□□□□	Provides detailed information on selecting, installing, and connecting linear motor.
	Direct Drive Motor	Direct Drive Motor User Manual	MR99UE01-□□□□	Provides detailed information on selecting, installing, and connecting direct drive motor.
	Torque Motor	Torque Motor User Manual	MW99UE01-□□□□	Provides detailed information on selecting, installing, and connecting torque motor.
	AC Servo Motor	AC Servo Motor User Manual	MC03UE01-□□□□	Provides detailed information on selecting, installing, and connecting AC servo motor.
	IM-1 Series Permanent Magnet Synchronous Spindle Motor	IM-1 Series Permanent Magnet Synchronous Spindle Motor User Manual	MS01UE01-□□□□	Provides detailed information on selecting and installing IM-1 series permanent magnet synchronous spindle motor.
Linear Motor Stage	Standard Single-Axis Linear Motor Stage	Standard Single-Axis Linear Motor Stage User Manual	MM06UE01-□□□□	Provides detailed information on selecting, installing, and connecting standard single-axis linear motor stage.
Actuator	Linear Actuator	Linear Actuator User Manual	MA99UE01-□□□□	Provides detailed information on selecting, installing, and connecting linear actuator.

Preface

Thank you for using this product. This manual provides information about the linear motor series. content include:

- Safety Precautions for Using Linear Motors
- Introduction to Linear Motors
- Linear Motor Selection
- Linear Motor Interface Design
- Linear Motor Installation
- Troubleshooting
- Maintenance
- appendix

Please read this manual carefully before use to ensure the correct use of the product.

Approvals

Motor Model	Approvals			
	EU Directives		UL Approvals	
LMSA	CE	RoHS	UL	cUL
LMSA-Z		RoHS		
LMFA	CE	RoHS	UL	cUL
LMFP	CE	RoHS	UL	cUL
LMSS	CE	RoHS	UL	cUL
LME	CE	RoHS	UL	
LMC	CE	RoHS		
LMT	CE	RoHS		

General Precautions

Before using the product, please carefully read through this manual. HIWIN Mikrosystem (HIWIN) is not responsible for any damage, accident or injury caused by failure in following the installation instructions and operating instructions stated in this manual.

- Before installing or using the product, ensure there is no damage to its appearance. If any damage is found after inspection, please contact HIWIN or local distributors.
- Do not disassemble or modify the product. The design of the product has been verified by structural calculation, computer simulation, and actual testing. HIWIN is not responsible for any damage, accident or injury caused by disassembly or modification done by users.
- Keep children away from the product.
- Anyone with a pacemaker or A.I.C.D is prohibited from using the product.
- The product should be operated only by personnel with experience and technical knowledge.

Discontinuation notice: The LMS and LMF series will be discontinued from April 2016. The original LMS series will be replaced by the LMSA series, and the original LMF series will be replaced by the LMFA series.

HIWIN offers 1-year warranty for the product. The warranty does not cover damage caused by improper usage (refer to the precautions and instructions stated in this manual) or natural disaster.

Safety Precautions

- Please read this manual carefully before installing, transporting, maintaining and inspecting the product to ensure proper use of the product.
- Please read the motor information, safety information and related precautions carefully before using the product.
- The safety precautions in this manual are divided into three categories: DANGER, WARNING and CAUTION.

DANGER

Imminent danger!

Indicates that death or severe personal injury will result if proper precautions are not taken.

WARNING

Potentially dangerous situation!

Indicates that death or severe personal injury may result if proper precautions are not taken.

CAUTION

Potentially dangerous situation!

Indicates that property damage or environmental pollution can result if proper precautions are not taken.

Chapter Overview

Chapter	Title	Contents
1	Introduction	This chapter introduces the basic information of linear motor, such as its structure, specification and model explanation.
2	Configuration	This chapter introduces the method of selecting linear motor.
3	Interface Design	This chapter introduces the interface design of linear motor.
4	Installation	This chapter introduces the conditions and precautions of installing linear motor.
5	Troubleshooting	This chapter introduces the actions when linear motor malfunctions.
6	Maintenance and Waste Disposal	This chapter introduces the way to maintain and scrap linear motor.
7	Appendix	This chapter introduces the glossary of linear motor, unit conversion and other supplementary contents.

Table of Contents

Revision History	ii
Related Documents	iv
Preface.....	vii
Approvals.....	viii
General Precautions	ix
Safety Precautions	x
Chapter Overview.....	xi
Table of Contents.....	xii
1. Introduction	1-1
1.1 Overview	1-2
1.1.1 Description of safety notices and safety symbols	1-2
1.1.2 Safety instructions.....	1-3
1.1.3 Intended use	1-6
1.1.4 Wiring precautions	1-7
1.1.5 Maintenance and storage precautions.....	1-7
1.1.6 Transport precautions	1-8
1.2 Features	1-10
1.2.1 An Introduction to linear motors	1-10
1.3 Model explanation	1-11
1.3.1 Type plate	1-11
1.3.2 Motor IP protection class	1-12
2. Configuration	2-1
2.1 Motor related	2-2
2.1.1 Linear motor selection	2-2
2.1.1.1 Iron core linear motor (LMSA/LME/LMSA-Z/LMSS) structure	2-3
2.1.1.2 Water-cooling linear motor (LMFA/LMFP) structure	2-5
2.1.1.3 Iron linear motor (LMSC) structure.....	2-7
2.1.1.4 Ironless linear motor (LMC) structure	2-8
2.1.1.5 Tubular linear motor (LMT) structure	2-10
2.1.1.6 Water-cooling linear motor cooling system	2-11
2.1.1.7 LMFC forcer precision water-cooling	2-12
2.1.1.8 LMFC stator precision water-cooling	2-12
2.1.2 Motor heat calculation	2-13
2.1.2.1 Motor heat loss.....	2-13
2.1.2.2 Continuous operating temperature	2-14
2.1.2.3 Thermal time constant.....	2-15
2.1.2.4 Stall conditions	2-17
2.1.2.5 Environmental temperature and Continuous force	2-19
2.1.2.6 Temperature sensor	2-20

2.1.2.7	Connection to the drive amplifier	2-22
2.1.2.8	Configuration of over-temperature protection.....	2-23
2.2	Servo drive related.....	2-24
2.2.1	Power supply and controller selection	2-24
2.2.2	Cable line voltage reflection phenomenon	2-27
2.3	Cooling related.....	2-28
2.3.1	Cooling system calculation	2-28
2.3.2	Cooling machine selection	2-30
2.3.3	Cooling power selection.....	2-31
2.3.4	Flow rate selection	2-33
3.	Interface Design	3-1
3.1	Interface design	3-3
3.1.1	Water cooling design.....	3-3
3.1.1.1	LMFA/LMFP Water-cooling motor cooling tube design	3-3
3.1.1.2	LMFA/LMFP water-cooling motor with LMFC precision water-cooling channel design	3-4
3.1.1.3	Material used in water-cooling channel	3-8
3.1.1.4	Coolant of water-cooling linear motor	3-8
3.1.2	Iron core linear motor assembly interface	3-10
3.1.2.1	LMSA iron core linear motor series	3-11
3.1.2.2	LMFA water-cooling linear motor series.....	3-12
3.1.2.3	LMSC double thrust linear motor series	3-15
3.1.2.4	LMSS iron core linear motor series.....	3-16
3.1.2.5	LME iron core linear motor series.....	3-17
3.1.3	Ironless linear motor (LMC) mechanical installation interface.....	3-18
3.1.4	Tubular linear motor (LMT) mechanical installation interface	3-19
3.2	Mounting	3-23
3.2.1	Force vs. air gap.....	3-23
3.2.1.1	LMSA Series	3-24
3.2.1.2	LMFA series.....	3-26
3.2.1.3	LMFP series.....	3-32
3.2.1.4	LMSC series.....	3-38
3.2.1.5	LME seires.....	3-39
3.2.2	Screw selection rules and instructions.....	3-43
3.2.2.1	Force and stator screw installation hole specification table.....	3-44
3.2.2.2	Forcer recommended screw fastening depth table.....	3-47
3.2.2.3	Stator recommended screw fastening minimum depth table	3-48
3.2.2.4	Forcer and stator recommended screw torque table	3-48
3.3	Electrical connection.....	3-49
3.3.1	Cable.....	3-49
3.3.1.1	Standard specification of power cable.....	3-49
3.3.1.2	Recommended construction method for grounding protection	3-49

3.3.1.3	Recommended construction method for ironless linear motor grounding protection	3-50
3.3.1.4	Recommended installation method of extension cable for LMSA-Z series	3-51
3.3.1.5	Motor with connector series	3-58
3.3.1.6	Connector selection and pin assignment.....	3-60
3.3.2	Forcer parallel design	3-64
3.3.2.1	Linear motor moving direction	3-65
3.3.2.2	LMSA/LMSA-Z/LME linear motor series	3-66
3.3.2.3	LMFA water-cooling linear motor series	3-67
3.3.2.4	LMSC magnetic brake linear motor series	3-68
3.3.2.5	LMSS linear motor series	3-69
3.3.2.6	LMC ironless linear motor series	3-70
3.3.2.7	LMT Tubular linear motor series.....	3-74
3.3.3	Hall accessories	3-77
3.3.3.1	Hall sensor	3-77
3.3.3.2	Hall sensor installation instructions.....	3-83
3.3.3.3	Selection of Hall sensor screws.....	3-84
3.3.3.4	Hall encoder	3-85
3.3.3.5	Hall encoder coding instructions	3-86
3.3.3.6	Hall encoder characteristic specification	3-87
3.3.3.7	Hall encoder dimension	3-88
4.	Installation	4-1
4.1	Mechanical installation	4-2
4.1.1	Iron core linear motor installation	4-2
4.1.1.1	Precautions for handling stator	4-2
4.1.1.2	Precautions for installation of forcer and stator	4-8
4.1.1.3	Precautions for installation of LMSC forcer and stator	4-14
4.1.2	Ironless linear motor installation	4-20
4.1.2.1	Precautions for installation of the LMC forcer and stator.....	4-20
4.1.2.2	Precautions for installation of LMT forcer and stator	4-25
4.1.3	Water-cooling linear motor cooling system installation.....	4-30
4.1.3.1	Forcer and stator precision water-cooling installation	4-30
4.1.3.2	Water-cooling motor quick connector installation	4-32
4.1.3.3	Precision water-cooling motor quick connector installation	4-33
5.	Troubleshooting	5-1
5.1	Troubleshooting	5-2
6.	Maintenance and Waste Disposal.....	6-1
6.1	Waste disposal	6-2
7.	Appendix.....	7-1
7.1	Glossary	7-2
7.2	Unit conversion	7-6
7.3	Customer request form.....	7-8

1. Introduction




<u>1.</u>	<u>Introduction</u>	1-1
<u>1.1</u>	<u>Overview</u>	1-2
<u>1.1.1</u>	<u>Description of safety notices and safety symbols</u>	1-2
<u>1.1.2</u>	<u>Safety instructions</u>	1-3
<u>1.1.3</u>	<u>Intended use</u>	1-6
<u>1.1.4</u>	<u>Wiring precautions</u>	1-7
<u>1.1.5</u>	<u>Maintenance and storage precautions</u>	1-7
<u>1.1.6</u>	<u>Transport precautions</u>	1-8
<u>1.2</u>	<u>Features</u>	1-10
<u>1.2.1</u>	<u>An Introduction to linear motors</u>	1-10
<u>1.3</u>	<u>Model explanation</u>	1-11
<u>1.3.1</u>	<u>Type plate</u>	1-11
<u>1.3.2</u>	<u>Motor IP protection class</u>	1-12

1.1 Overview








1.1.1 Description of safety notices and safety symbols

Safety notices are always indicated using a signal word and sometimes also a symbol for the specific risk.

The following signal word and risk levels are used:

 DANGER
Imminent danger! Indicates that death or severe personal injury will result if proper precautions are not taken.
 WARNING
Potentially dangerous situation! Indicates that death or severe personal injury may result if proper precautions are not taken.
 CAUTION
Potentially dangerous situation! Indicates that property damage or environmental pollution can result if proper precautions are not taken.

The following symbols are used in this user manual:

Warning Signs			
	No access for people with active implanted cardiac devices.		Substance hazardous to the environment!
	Warning!		Warning of crushing of hands!
	Warning of electricity!		Warning of hot surface!
	Warning of magnetic field!		

1.1.2 Safety instructions

DANGER



Risk of death as a result of permanent magnet fields.

Even when the motor is switched off, the permanent magnets can put people with active medical implants at risk if they are close to the motor.

Stator assembly has a strong magnetic field; users must handle with care. Otherwise, personnel may get injured and the stator may be damaged.

- ◆ During assembly of stator to system structure, keep any magnetic material at a distance to prevent the risk of injury to hands.
- ◆ Do not touch the forcer and stator during operation.
- ◆ If you are affected, stay at a minimum distance of 500 mm from the motors (trigger threshold for static magnetic fields of 0.5 mT as per directive 2013/35/EU).

WARNING



Risk of Linear motor assembly.

Danger of crushing by permanent magnets of the stator.

The attraction forces of the stator act on materials that can be magnetized. The forces of attraction increase significantly close to the stator.

There is a significant risk of crushing when you are close to the stators.

Close to the stators, the forces of attraction can be several kN - example: magnetic attractive forces are equivalent to a force of 100 kg, which is sufficient to trap a body part.

- ◆ The product should be installed and operated by specialized personnel.
- ◆ During assembly, avoid using magnetic tools and screws.
- ◆ Before fixing the stator, please adhere the label of strong magnetic field to the position where it can easily be seen to prevent personnel from injury.
- ◆ Whenever disassembling the stator, do not handle the stator with the edge of the cover directly. Otherwise, personnel may get injured and the stator may be damaged.
- ◆ Never unpack several secondary sections at the same time.
- ◆ Never place secondary sections next to one another without taking the appropriate precautions.

 **WARNING**

Risk of Linear motor operate.

When incorrectly operated and in the case of a fault, the motor can overheat resulting in fire and smoke. This can result in severe injury or death.

Excessively high temperatures destroy motor components and result in increased failures as well as shorter service lives of motors.



- ◆ Operate the motor according to the relevant specifications.
- ◆ Allow the forcer to cool down sufficiently (in a 25°C room temperature) before working around the product to avoid burns.
- ◆ When an abnormal smell, noise, smoke, or vibration is detected, please turn off the power immediately.

 **WARNING**

Burn injuries caused by hot surfaces.

In operation, the motor can reach high temperatures, which can cause burns if touched.



- ◆ Operate the motor according to the relevant specifications.
- ◆ Allow the motor to cool down before starting any work.
- ◆ Use the appropriate personnel protection equipment, e.g., gloves.

 **CAUTION**

Damage caused by assembly.

Electric fields or electrostatic discharge can cause malfunctions through damaged Individual components, integrated circuits, modules or devices.



- ◆ Keep magnetic storage media or precision instruments away from the product to avoid damage-caused fields. (e.g., magnetic scale, watch, credit card and magnetic response device).
- ◆ Precautions should be taken for ESD (Electrostatic Discharge), like wearing gloves, shoes, etc.
- ◆ Do not drag the cables while moving or placing the forcer and stator units.
- ◆ Do not damage or bend the cables to avoid electric shock.
- ◆ Be sure to confirm that there is no interference with other components in the operations. Confirm that the cable bending radius is large enough to prevent reducing the lifetime of the cables.

⚠ CAUTION



Product precautions.

Product appearance description and avoid damage caused by improper disassembly.

- ◆ Clean stator surface by using disposable cotton rags and cleaning liquid such as isopropanol alcohol (95% Vol.). It is suggested to clean the surface once every three months or once every two weeks in high fume formation rate facilities with machines such as PCB machines or drilling machines.
- ◆ The products with epoxy have some spots on the surface, and it is a natural phenomenon.
- ◆ The product can only be repaired by HIWIN engineers. Please send the product back to HIWIN if there are any unusual occurrences.
- ◆ Do not change or disassemble the components by yourself. HIWIN will not take responsibility for any accidents or damages to theforcer and stator caused by this.
- ◆ A one-year guarantee is provided from the date of delivery. HIWIN will not be held responsible for replacing or maintaining a product which has been incorrectly handled (please refer to the notes and instructions in this manual) or damaged due to natural disasters.

- When taking or placing the product, do not just pull the cable and drag it.
- Do not subject the product to shock.
- Ensure the product is used with rated load.
- According to IEC 60034-5 standard, HIWIN linear motor has the class of protection (refer to section 1.3.2).
- HIWIN linear motor has a thermal class F according to IEC 60085 standard.
- HIWIN linear motor certification test meets the following standards.

Table 1.1.2.1

CE	LVD Safety: 2014/35/EU reference standard	EN60034-1:2010
	EMC: 2014/30/EU reference standard	EN61000-6-4:2007/A1:2011
		EN61000-6-2:2005
UL	Linear motor reference standard 1004-1	

1.1.3 Intended use

- Only use the motors for industrial systems.
- The motor must avoid dirt and contact with corrosive or abrasive substance, If the area where the motor is installed is polluted and dirt, then the motor can malfunction.
- Keep the area where the motor is installed free of all dirt and pollution.
- Do not install the motors in hazardous zones, if the motors have not label and description.
- Ensure that the installation conditions conform the specifications.
- For occasional exposure to liquids, the segmented cover offers less protection against liquid accumulating between the cover and the secondary sections. It can be advantageous not to use the cover in the case of substances that can attack or penetrate the encapsulation of the secondary sections and damage the magnet material. This allows any liquid to escape and the parts to dry.
- The Linear motor systems must not be operated:
 - (1). Outdoors.
 - (2). In potentially explosive atmospheres.

1.1.4 Wiring precautions

- Before using the product, carefully read through the specification noted on the product label, and ensure the product is used with power supply specified in the product requirement.
- Check if the wiring is correct. Incorrect wiring may make the motor operate abnormally, or even cause permanent damage to the motor.
- Select extension cord with shielding. The shielding must be grounded.
- Do not connect power cable and temperature sensor cable to the same extension cord.
- Power cable and temperature sensor cable contain shielding. The shielding must be grounded.

1.1.5 Maintenance and storage precautions

WARNING

Product precautions.

If you do not correctly dispose of direct drives or their components (especially components with permanent magnets), then this can result in death, severe injury and/or material damage.



- ◆ Disposal method of the damaged product: recycle it according to local laws and regulations.
- ◆ Refer to chapter 6 for related disposal methods.

Please follow below instructions as to the storage of HIWIN linear motors:

- Clean and protect used linear motors before storage.
- Store the Linear motor components in their transport packaging, and place horizontally not vertically and no stacked on top of each other.
- The motor cable should not be placed under the motor.
- Do not store the linear motor components in explosive atmospheres or in environments exposed to chemicals.

- Only store the linear motor components in dry, frost-free areas with a corrosion-free atmosphere, and Make sure that the motors are not subjected to vibrations or impacts while in storage.
- The stator must be separated and wrapped in a non-magnetic protective device with a thickness of more than 40 mm (e.g., Styrofoam). When storing the components, attach signs warning of magnetic fields.
- For long-term storage or in tropical countries, it is recommended to use anti-rust packaging for this product.
- Do not keep any metal objects close to the product to avoid damage to the objects.

Table 1.1.5.1

Operating environment	Temperature	0~40°C
	Humidity	5~85%
Storage environment	Temperature	-5°C ~40°C
	Humidity	5~85%
Altitude		Below 1000M
Temperature variation speed		Maximum 0.5K/min
Condensation		Not allowed
Frozen		Not allowed

1.1.6 Transport precautions

- Permanent magnets are listed as Dangerous Goods (Magnetized material: UN2807) according to International Air Transport Association (IATA).
- For products containing permanent magnets, no additional measures on packaging are required to resist the magnetic field in sea freight and inland transportation.
- When transporting products containing permanent magnets by air, the maximum permissible magnetic field strengths specified by the appropriate IATA Packing Instruction must not be exceeded. Special measures may be required so that these products can be shipped. Above a certain magnetic

field strength, such shipments must be labelled in accordance with Packing Instruction 953 from IATA (Please refer below or the latest regulation from IATA.)

- (1). Products whose highest field strength exceeds $0.418 \text{ A m} / (0.525 \mu\text{T})$ or 2° of compass deviation, as determined at a distance of 4.6M from the product, require shipping authorization from the responsible national body of the country from where the product is being shipped (country of origin) and the country where the airfreight company is based. Special measures need to be taken to enable the product to be shipped.
 - (2). When shipping products whose highest field strength is equal to or greater than $0.418 \text{ A m} / (0.525 \mu\text{T})$ or 2° of compass deviation, as determined at a distance of 2.1M from the product, shipment is conducted with regulation of Dangerous Goods Transportation.
 - (3). When shipping products whose highest field strength is less than $0.418 \text{ A m} / (0.525 \mu\text{T})$, as determined at a distance of 2.1M from the product, you do not have to notify the relevant authorities and you do not have to label the product.
- Shipping originally packed motor components neither has to be disclosed nor marked.
 - Transport conditions must comply with EN 60721-3-2 (Please refer table 1.1.6.1 on the next page).

Table 1.1.6.1 Transport conditions

Environmental parameter	Unit	Value
Air temperature	(°C)	-5~40
Relative humidity	(%)	5~85
Rate of change of temperature	(°C/min)	0.5
Condensation		Not allowed
Formation of ice		Not allowed
Transport condition		Class 2K2
Transport the motor in an environment with good weather protection (indoor/factory)		
Biological conditions	Class 2B1	
Chemically active substances	Class 2C1	
Mechanically active substances	Class 2S2	
Mechanical conditions	Class 2M2	

1.2 Features

1.2.1 An Introduction to linear motors

Linear motors can be divided into iron core and ironless linear motors. An iron core linear motor has a relatively greater thrust force, and an ironless linear motor is relatively more compact with greater dynamic characteristics. Since there is no transmission mechanism between the motor and the load, the load can be driven directly. Accordingly, the mechanism is relatively simple and a remarkable dynamic response can be achieved. Furthermore, linear motors adopt the contactless design such that there is no wear and higher precision can be provided while the maintenance and care required can also be reduced. The stator of a linear motor adopts the module assembly method and the number of acceptable assemblies is unlimited such that the length of the stroke is not restricted.

1.3 Model explanation

1.3.1 Type plate

- Information about the type plates for the different motor types. (Type plate example)
- The continuous force and continuous current value of LMFA(P) are in water cooling. Ant the other type of motor(LMSA/LMC/LMT/LMSS/LME) specifications are in natural cooling.




Figure 1.3.1.1 Type plate example

1.3.2 Motor IP protection class

Linear motor applies to IEC to define the protection class. The first number of IP□□ means the protection class against dust ingress. Class 6 refers to total protection against dust ingress. The second means protection class against water ingress. Class 0 means no protection. Class 5 means protection against low pressure water jets from any direction. Class 6 means protection against high pressure water jets from any direction.

- IP protection class for different motor types.

Table 1.3.2.1

Linear motor	Protection class
LMSA	IP60
LMFA	IP60
LMFP	IP65
LMSC	IP60
LMC	IP60
LMSS	IP60
LME	IP60
LMT	IP66

The stators are largely protected against corrosion by their mechanical design. However, suitable constructive measures have to be taken to prevent that ferromagnetic particles (for example, iron chips) accumulate on the stator. Contact with liquids and general contact with corrosive media must be avoided by suitable protective measures (encapsulation, bellows, protective lacquer).

2. Configuration

2.	.Configuration	2-1
2.1	Motor related	2-2
2.1.1	Linear motor selection	2-2
2.1.1.1	Iron core linear motor (LMSA/LME/LMSA-Z/LMSS) structure	2-3
2.1.1.2	Water-cooling linear motor (LMFA/LMFP) structure	2-5
2.1.1.3	Iron linear motor (LMSC) structure	2-7
2.1.1.4	Ironless linear motor (LMC) structure	2-8
2.1.1.5	Tubular linear motor (LMT) structure	2-10
2.1.1.6	Water-cooling linear motor cooling system	2-11
2.1.1.7	LMFC forcer precision water-cooling	2-12
2.1.1.8	LMFC stator precision water-cooling	2-12
2.1.2	Motor heat calculation	2-13
2.1.2.1	Motor heat loss	2-13
2.1.2.2	Continuous operating temperature	2-14
2.1.2.3	Thermal time constant	2-15
2.1.2.4	Stall conditions	2-17
2.1.2.5	Environmental temperature and Continuous force	2-19
2.1.2.6	Temperature sensor	2-20
2.1.2.7	Connection to the drive amplifier	2-22
2.1.2.8	Configuration of over-temperature protection	2-23
2.2	Servo drive related	2-24
2.2.1	Power supply and controller selection	2-24
2.2.2	Cable line voltage reflection phenomenon	2-27
2.3	Cooling related	2-28
2.3.1	Cooling system calculation	2-28
2.3.2	Cooling machine selection	2-30
2.3.3	Cooling power selection	2-31
2.3.4	Flow rate selection	2-33

2.1 Motor related

2.1.1 Linear motor selection

According to the industrial applications, they can be mainly divided into the point-to-point movement and scanning application. Iron core linear motors are suitable for the application of point-to-point movement, and ironless linear motors are suitable for the scanning application, as shown in figure 2.1.1.1.



Figure 2.1.1.1 Linear motor application illustration images

2.1.1.1 Iron core linear motor (LMSA/LME/LMSA-Z/LMSS) structure

LMSA/LME/LMSA-Z/LMSS product is an iron core motor, and the forcer consists of an iron core, coil and epoxy assembled together. Since the iron core interacts with the magnet, this series of motor is affected by the cogging force and the attraction force between the forcer and stator. Accordingly, during the design of the forcer installation base, it is necessary to consider such factors. This product is suitable to be used for high acceleration and deceleration applications, such as: conveyor/transportation equipment, digital printing, 3D printing, PCB drilling machine, light processing machine etc.




Figure 2.1.1.1.1 Forcer structure

The stator of LMSA/LME/LMSA-Z/LMSS, as viewed from the top, is of a rectangular structure. Customers can select the cover or epoxy version of the stator according to the industrial application. In addition, the stator can also be used as a moving part.




Figure 2.1.1.1.2 Stator structure

The stator polarity description is shown in the figure 2.1.1.1.3, and the moving direction please refer to chapter 3.3.2.1.





Figure 2.1.1.1.3 Stator polarity

During the installation of the motor, please be aware of the air gap between theforcer and the stator. For the relationship between the air gap of an iron core linear motor and the motor performance, please refer to section 3.2.1 of the manual.

For the installation guidelines on the forcer and stator of the motor, please refer to section 4.1.1 of the manual. Since a strong attraction force exists between the forcer and stator, please do not arbitrarily remove the stator and do not use magnetic material to approach the device in order to prevent any danger. In addition, the stator assembly length must be greater than the length of the forcer; otherwise, unexpected risk may occur.

LMSA/LME/LMSS



LMSA-Z




Figure 2.1.1.1.4 Forcer and stator structure

2.1.1.2 Water-cooling linear motor (LMFA/LMFP) structure

LMFA/LMFP product is an iron core water-cooling motor, and the forcer consists of an iron core, forcer base, coil, cooling copper tube and epoxy assembled together. Since the iron core interacts with the magnet, this series of motor is affected by the cogging force and the attraction force between the forcer and stator. Accordingly, during the design of the forcer installation base, it is necessary to consider such factors. This product utilizes a cooling system to increase the motor performance, and it is suitable to be used for heavy load applications, such as: conveyor/transportation equipment, PCB drilling machine, grinding machine etc.




Figure 2.1.1.2.1 Forcer structure

The stator of LMFA/LMFP, as viewed from the top, is of a rectangular structure. Customers can select the Cover or Epoxy version of the stator according to the industrial application.




Figure 2.1.1.2.2 Stator structure

The stator polarity description is shown in the figure 2.1.1.2.3, and the moving direction please refer to chapter 3.3.2.1.




Figure 2.1.1.2.3 Stator polarity

During the installation of the motor, please be aware of the air gap between theforcer and the stator. For the relationship between the air gap of an iron core linear motor and the motor performance, please refer to section 3.2.1 of the Manual.

For the installation guidelines on the forcer and stator of the motor, please refer to section 4.1.1 of the Manual. Since a strong magnetic attraction force exists between the forcer and stator, please do not arbitrarily remove the stator and do not use magnetic material to approach the device in order to prevent any danger. In addition, the stator assembly length must be greater than the length of the forcer; otherwise, unexpected risk may occur.




Figure 2.1.1.2.4 Forcer and stator structure

2.1.1.3 Iron linear motor (LMSC) structure

LMSC product is an iron core motor, assembled by iron core, forcer base, coil and epoxy. Since the iron cores are arranged back-to-back, the attraction force between forcer and stator could be offset, load on guideway is greatly reduced and the lifetime of the guideway could be extended.

This product is suitable to be used for high acceleration applications such as conveyor / transportation equipment, automation production line and lightweight processing equipment.




Figure 2.1.1.3.1 Forcer structure

2.1.1.4 Ironless linear motor (LMC) structure

LMC product is an ironless motor. From the force assembly drawing of figure 2.1.1.4.1, it can be understood that the internal of the forcer does not consist of an iron core but coil only, such that it is formed by a forcer base and epoxy assembled together. Since it is an ironless structure, this series of motor has no cogging force, no attraction force between the forcer and stator, and has the characteristic of low inertia. It is suitable to be used for applications of high speed and light load and applications requiring extremely low-speed ripple and low magnetic field dissipation, such as: optical inspection equipment, scanning type electronic microscope equipment etc.




Figure 2.1.1.4.1 Forcer structure

The stator of LMC, as viewed from the side, is a U-shape structure, and it consists of a base and two rows of magnets assembled together as shown in figure 2.1.1.4.2. Since the quantity of the magnets is greater than the iron core linear motor, its overall weight is heavier than the forcer. Accordingly, customers are not required to use the stator as a moving part.




Figure 2.1.1.4.2 Stator structure

The stator polarity description is shown in the figure 2.1.1.4.3, and the moving direction please refer to chapter 3.3.2.1.




Figure 2.1.1.4.3 Stator polarity

The cut-out portion of the U-shape structure of the LMC stator is to allow theforcer to move between the stator. During the installation of the motor, please be aware of the assembly gap between the stator, as shown in figure 2.1.1.4.3. For the installation guidelines for the motor forcer and stator, please refer to section 4.1.2 of the Manual. Since the magnets used by the stator are of strong magnetic attraction force, please do not arbitrarily remove the stator or use magnetic material to approach the stator in order to prevent any danger.




Figure 2.1.1.4.4 Forcer and stator structure

2.1.1.5 Tubular linear motor (LMT) structure

The LMT series product of the Company is an ironless tubular motor. Due to the ironless structure, the motor characteristics are consistent with the characteristics of the LMC series, such that it not has cogging force, the Attraction force, and has the characteristic of low inertia. The forcer assembly is as shown in figure 2.1.1.5.1, and its internal structure is ironless. The difference between LMT and LMC relies on that LMT is a relatively more compact simple structure with an outer appearance resembling a screw tubular linear mechanism, making it easy for maintenance and the mechanism space utilization rate can be increased. For customers changing from screw tubular linear mechanism to direct drive linear mechanism, it is the most optimal solution for use. Its common application includes: optical inspection equipment, machine tool wire cutting equipment, scanning electronic microscope equipment, food automation equipment and medical automation industry etc.




Figure 2.1.1.5.1 Forcer structure

The outer appearance of LMT stator is a sealed circular rod, and it is formed by the stator outer tube and magnets, as shown in figure 2.1.1.5.2. During the motor installation, please be aware of the assembly gap between the forcer and stator, as shown in figure 2.1.1.5.3. For the installation guidelines for the motor forcer and stator, please refer to section 4.1.2 of the Manual. Since the magnets used by the stator are of strong magnetic attraction force, please do not arbitrarily remove the stator or use magnetic material to approach the stator in order to prevent any danger.




Figure 2.1.1.5.2 Stator structure




Figure 2.1.1.5.3 Forcer and stator structure

2.1.1.6 Water-cooling linear motor cooling system

HIWIN LMFA/LMFP series motor adopts the internal water-cooling method to achieve the most optimal motor performance. In addition to the internal water-cooling, LMFA/LMFP series motor is also equipped with the option of LMFC precision water-cooling accessory capable of increasing the heat exchange area and isolating the heat transfer from the motor, in order to significantly reduce the temperature of the machinery of customers. The temperature distribution comparison is as shown in figure 2.1.1.6.1, thereby satisfying the application demand of high precision. Its structure is as shown in figure 2.1.1.6.2.




Figure 2.1.1.6.1 Temperature distribution comparison image




Figure 2.1.1.6.2 LMFA/LMFP series with LMFC precision water-cooling motor basic structure

2.1.1.7 LMFC forcer precision water-cooling

The internal LMFA/LMFP series motor is equipped with coolant channels, and the coolant enters into the internal of the motor from the water-cooling connector inlet to perform cooling. After passing through the sealed channels for heat dissipation, the coolant returns back to the water-cooling machine via the water-cooling connector outlet. For a motor equipped with the LMFC forcer precision water-cooling, a LMFC precision water-cooling accessory is installed on top of the original LMFA/LMFP forcer. The insulation material provided for the precision water-cooling is used to isolate the heat transfer. The coolant enters into the motor to perform cooling via the water-cooling connector inlet, and after passing through the sealed channels for heat dissipation, it then returns back to the water-cooling machine via the water-cooling connector outlet.

2.1.1.8 LMFC stator precision water-cooling

The cooling design for the heat dissipation of the stator is only provided for the LMFC precision water-cooling series. The LMFC stator precision water-cooling is installed underneath the LMFA/LMFP stator. The coolant enters into the motor to perform cooling via the water-cooling connector inlet, and after passing through the sealed channels for heat dissipation, it then returns back to the water-cooling machine via the water-cooling connector outlet in order to achieve fast heat dissipation effect.

2.1.2 Motor heat calculation

2.1.2.1 Motor heat loss

During the process of converting electrical energy into kinetic energy of a motor, it is inevitable that copper loss, iron loss and mechanical loss also occur; where copper loss refers to the loss caused by the resistance as current passes through the motor forcer coil; iron loss is caused by the magnetic field conversion between the forcer and stator magnets; and mechanical loss is, in general, far less than the copper and iron losses such that it can be omitted.

The copper loss calculation method under the Continuous force is:

$$P_C = \frac{3}{2} \times R_{25} \times \{1 + [0.00393 \times (T_{max} - 25)]\} \times I_C^2$$

P_C : Copper loss when the coil temperature is T_{max} [W]

R_{25} : Line-to-line resistance when the coil temperature is 25°C [Ω]

I_C : Continuous current when the coil temperature is T_{max} [A_{rms}]

T_{max} : Maximum winding temperature [°C] (please refer to the catalog of each series motor)

Heat loss mainly utilizes the thermal conduction method to transfer the loss of the coil to the motor surface. In an example of natural air cooling, the heat loss source is transferred to the external environment via heat convection from the motor surface in contact with the air, and the heat is further transferred away through heat radiation and thermal conduction from the installation surface of customers. In an example of water-cooling, the heat loss source utilizes thermal conduction to transfer heat from the heat source center to the cooling water, and since cooling water has a heat convection coefficient much higher than that of air, the effect of heat transfer from the heat source to the air via convection can be omitted. The cooling method for LMFA series motors can use the water-cooling or air-cooling type. Please ensure that the parameters used are the same as the ones indicated in the specification, and please also be aware that the Maximum winding temperature shall not exceed 120°C.

2.1.2.2 Continuous operating temperature

The motor coil steady-state temperature is defined based on the ratio of copper and iron losses. When a linear motor is used, iron loss can be omitted. The motor total loss and rated Continuous force (F_c) are both defined according to the Maximum winding temperature specified in the catalog. When an equivalent thrust force (F_e) is smaller than the rated Continuous force (F_c), the steady-state temperatures of the motor coil under different operational conditions can be obtained from the following formula.

When the operating current is lower than the rated current ($I_e \leq I_c$), its relationship between temperature and thrust force is

$$T_e = T_{amb} + \left(\frac{F_e}{F_c} \right)^2 \times (T_{max} - 25)$$

T_e : Coil steady-state temperature under equivalent thrust force [°C]

T_{amb} : Environmental temperature [°C]

F_e : Equivalent thrust force of actual operation [N] (when coil temperature is T_e)

F_c : Rated Continuous force [N] (when the coil temperature is T_{max})

2.1.2.3 Thermal time constant

During the operating process of a motor, its coil temperature is related to the thermal time constant. The thermal time constant is defined to be the time (as shown in figure 2.1.2.3.1) when the temperature difference between the coil initial temperature T_0 and the Maximum winding temperature T_{max} reached is 63%. The time for the motor to reach the steady state is approximately 5 times the thermal time constant t_{TH} .




Figure 2.1.2.3.1 Motor temperature increase curve graph

The equation between the thermal time constant and temperature is

$$T(t) = T_0 + (T_{max} - T_0) \times \left(1 - e^{-\left(\frac{t}{t_{TH}}\right)}\right)$$

$T(t)$: Coil temperature [°C] (at operating time t)

T_0 : Coil initial temperature [°C]

T_{max} : Maximum winding temperature [°C]

t_{TH} : Thermal time constant [sec] (please refer to catalog for each series motor)

t : Operating time [sec]

When the operating current is between the rated current and peak current ($I_c < I_e < I_p$), it is necessary to set up the power off idleness time to allow the motor to cool down. In addition, the aforementioned thermal time constant can be used for calculating the time required for the load cycle. First, according to section 2.1.2.2, the equivalent thrust force of actual operation (F_e) is used to obtain the coil steady-state temperature (T_e) value under the equivalent thrust force, following which the following equation is then used to obtain the relative maximum operating time.

The equation for the coil steady-state temperature (T_e) under the equivalent thrust force and the maximum operating time is

$$t = -t_{TH} \times \ln \left(1 - \frac{T_e - T_0}{T_{max} - T_0} \right)$$

t : Maximum operating time [sec]

Note: The coil temperature (T_e) of the equivalent current described here shall not exceed the Maximum winding temperature (T_{max}) specified in the catalog.

2.1.2.4 Stall conditions

When the motor speed is extremely slow (including standstill), the current commutation speed inside the motor is very slow, the current will accumulate in certain sets of coils inside the motor. If continuous current is used at this time, it will eventually lead to insufficient heat dissipation, which will end up the motor overheat.

The concept is as followings, Figure 2.1.2.4.1:

- The arrow is like a water flow around the motor for heat dissipation, and the amount of water that can flow out per unit of time is fixed.
- When under stall condition, the temperature of the motor will be concentrated on a certain two phases or a certain phase of the motor.
- The water flow around the motor has not increased, so the heat of the motor will continue to accumulate in some coils.




Figure 2.1.2.4.1 Normal operation (Left). Stall condition (Right)

When the motor operates at a motor frequency lower than 1 Hz, it is regarded as stall condition.

The relationship between motor frequency, motor speed and the number of poles is as follows:

$$v = 2 \tau f$$

v = velocity (m/s)

f = Electrical frequency (Hz)

2τ = pole pair pitch (m)




Figure 2.1.2.4.2 Current in motor at different phase

At mentioned earlier, when the motor speed is extremely low and the motor is operating in stall condition, the current will exceed the continuous current that each phase can withstand on two-phase or single-phase as shown in Figure 2.1.2.4.2, the operating current must be properly reduced to avoid overheating. There are two boundaries in the stalled condition. At any electrical angle, the current must be between the following two cases:

Case1 Overcurrent on both phases. (Example of U, W phase)

➔ Current down to **81%** continuous current ($\frac{1}{\sqrt{1.5}}$)

➔ Modify Current: $I_{phase_U} = I_{phase_W} = \frac{1}{\sqrt{1.5}} I_c(w)$

Case 2 Overcurrent on single phase. (Example of V phase)

➔ Current down to **70%** continuous current ($\frac{1}{\sqrt{2}}$)

➔ Modify current: $I_{phase_U} = \frac{1}{\sqrt{2}} I_c(w)$

Stall condition is easily ignored by users in application and calculation. If the motor speed is lower than the speed shown in Table 2.1.2.4.1, it must be regarded as a stall condition. The operation conditions must be carefully estimated. Current and temperature must be monitored. This is to prevent the motor from getting damaged by overheating.

Table 2.1.2.4.1 Stall Speed of HIWIN Linear motor

LM series	LMSA/LME	LMFA0□~2□, LMFP2□	LMFA3□~6□, LMFP3□~6□
Velocity (m/s)	0.03	0.03	0.046
LM series	LMSS	LMCA, LMCB, LMCC	LMCD, LMCE, LMCf, LMC-EFC, LMC-EFE, LMC-EFF
Velocity (m/s)	0.02	0.032	0.06
LM series	LMC-HUB	LMT2	LMT6
Velocity (m/s)	0.024	0.048	0.06
LM series	LMTA	LMTB	LMTC
Velocity (m/s)	0.072	0.09	0.12

2.1.2.5 Environmental temperature and Continuous force

HIWIN linear motor Continuous force is defined based on the Maximum winding temperature of such series motors reached under the environmental temperature of 25 °C . When the operating environmental temperature exceeds 25 °C , the Continuous force achievable by the motor is reduced. Under different environmental temperatures, the Continuous force that can be achieved without having the motor exceeding the Maximum winding temperature under different environmental temperatures can be calculated from the following formula.

$$\frac{T_{max} - T_{amb}}{T_{max} - T_0} = \frac{F_x^2}{F_C^2}$$

T_{max} : Maximum winding temperature (catalog value) [°C]

T_{amb} : Environmental temperature [°C]

T_0 : Motor initial temperature [°C], water-cooling $T_0=20^{\circ}\text{C}$, natural-cooling $T_0=25^{\circ}\text{C}$

F_C : Continuous force (catalog value) [N]

F_x : Achievable Continuous force under different environmental temperatures [N]

The relationship between different environmental temperatures and achievable Continuous force is as shown in figure 2.1.2.5.1 and figure 2.1.2.5.2.




Figure 2.1.2.5.1 Environmental temperature v.s. Continuous force relationship graph with natural-cooling motor




Figure 2.1.2.5.2 Environmental temperature v.s. Continuous force relationship graph with water-cooling motor

2.1.2.6 Temperature sensor

Linear motors are built-in with a temperature sensor to provide signal to the control system in order to achieve necessary motor over-temperature protection.

Motor protection by temperature monitoring alone using PTC elements can be insufficient. This is the case, for example, if the motor is operated with currents above continuous current. HIWIN advises the use of additional protective algorithm on the control side. The calculation of max. operating time with currents above continuous current can refer to section 2.1.2.3 .

The common temperature sensors include PTC, Pt1000 etc. For the type of temperature sensors equipped in a motor, please refer to the catalog or acceptance drawings, and the performance of temperature sensors is described in the following respectively:

PTC 100 and PTC 120 are a thermistor respectively, and their output resistance changes along with the temperature of the coil. The resistance of PTC 100 increases significantly when $T_{REF} = 100^{\circ}\text{C}$, and the resistance of PTC 120 increases significantly when $T_{REF} = 120^{\circ}\text{C}$. Their characteristics are as follows.

Table 2.1.2.6.1 PTC temperature sensor characteristics

Temperature	Resistor
$20^{\circ}\text{C} < T < T_{REF} - 20\text{K}$	$20\Omega\sim 250\Omega$
$T = T_{REF} - 20\text{K}$	$\leq 550\Omega$
$T = T_{REF} + 5\text{K}$	$\geq 1330\Omega$
$T = T_{REF} + 15\text{K}$	$\geq 4000\Omega$




Figure 2.1.2.6.1 PTC temperature to resistance relationship graph

Pt1000 is a platinum resistor temperature sensor (RTD), and its characteristic is that when the temperature is 0°C, its resistance is 1000Ω. The actual temperature can be obtained by measuring the output resistance. The resistance and temperature relationship is as shown in figure 2.1.2.6.2, and the standard equation between the resistance and temperature is expressed in the following:

When the temperature range is -200 ~ 0°C

$$R_{\theta} = R_0[1 + A\theta + B\theta^2 + C(\theta - 100)\theta^3]$$

When the temperature range is 0 ~ 850°C

$$R_{\theta} = R_0(1 + A\theta + B\theta^2)$$

$$R_0 = 1000 \text{ } [\Omega]$$

θ =Operating temperature [°C]

$$A = 3.9083 \times 10^{-3} \text{ } [^{\circ}\text{C}^{-1}]$$

$$B = -5.7750 \times 10^{-7} \text{ } [^{\circ}\text{C}^{-2}]$$

$$C = -4.1830 \times 10^{-12} \text{ } [^{\circ}\text{C}^{-4}]$$




Figure 2.1.2.6.2 Pt1000 resistance and temperature relationship graph

KTY84-130 is a silicon temperature sensor, and the actual temperature can be obtained by measuring the output resistance. Its characteristic is as shown in table 2.1.2.6.2 and the relationship between the resistance and temperature is as shown in figure 2.1.2.6.3

Table 2.1.2.6.2 KTY84-130 temperature sensor characteristics

Symbol	Parameter	Criteria	Minimum value	Standard value	Maximum value	Unit
R_{100}	Resistance when temperature below 100°C	$I_{(out)} = 2mA$	970	-	1030	Ω
R_{250} / R_{100}	Resistance ratio	T = 250°C and 100°C	2.111	2.166	2.221	Ω
R_{25} / R_{100}	Resistance ratio	T = 25°C and 100°C	0.595	0.603	0.611	Ω




Figure 2.1.2.6.3 KTY84-130 resistance and temperature relationship graph

2.1.2.7 Connection to the drive amplifier

The temperature monitoring circuits can normally be connected directly to the drive control. If the protective separation requirements in accordance with EN61800-5-1 are to be fulfilled, the sensors must be connected to the decoupling modules provided by the drive manufactures.

2.1.2.8 Configuration of over-temperature protection

Table 2.1.2.8.1 Over-temperature protection configuration chart

	Configuration diagram
PTC SNM120	<div><div>T1 – (yellow) T1 + (red)</div><div><div>Phase 1</div><div>Phase 2</div><div>Phase 3</div></div></div>
PT1000	<div><div>T2 + (black) T2 – (white)</div><div></div></div>
SKM120	<div><div>T – (blue) T + (brown)</div><div><div>Phase 1</div><div>Phase 2</div><div>Phase 3</div></div></div>

2.2 Servo drive related

2.2.1 Power supply and controller selection

The continuous current, peak current and bus voltage must be considered while selecting a power supply. In addition, the resonance effect which can be induced in motors by some drive systems must be taken into account. Motors are assembled with several individual coils connected in series. Each one of these coils has an inductance in series and a stray capacitance to earth. The LC network obtained possesses a resonant frequency, so when an electrical oscillation is applied to the phase inputs (in particular the PWM frequency), the neutral point of the motor can oscillate with very high amplitudes with respect to earth, and the insulation can be damaged as a consequence of these oscillations. This phenomenon is more pronounced in motors with a large number of poles (such as linear motors).

Under ideal conditions, the 600 V_{DC} bus voltage generated by the power supply should be ± 300 V_{DC} relative to earth. However, in some configurations, the voltage between the buses and earth will have an oscillating voltage, and the peak of the high voltage will be transmitted to the motor. The oscillation between voltage and earth depends on system characteristics. By experience, a system with few axes connected to the bus voltage is less liable to have disturbing oscillations on the bus, but for example in a large machine tool with many axes and several spindles, the oscillations can reach high amplitudes. If the frequency of these oscillations is close to the resonant frequency of the motor, it can lead to over-voltage failures on the neutral point.

The case where the PWM frequency of the controller happens to correspond to the resonant frequency of the motor. In this case, the fundamental harmonic of the PWM frequency is directly exciting the resonant frequency of the motor, and very high voltages are thus obtained on the neutral point. Also, as the PWM voltage is a square wave, it contains odd harmonics (1, 3, 5, 7, etc..) that can also excite the motor resonance. Fortunately, these harmonics have a smaller amplitude than the fundamental.

In another case, it may also lead to an over-voltage failure. In this case, the fundamental harmonic of the PWM frequency is directly exciting the resonant frequency of the motor, and very high voltages are thus obtained on the neutral point. In addition, because the PWM voltage is a square wave, it contains odd harmonics (1, 3, 5, 7, etc..) that can also excite motor resonance. In conclusion, to prevent any failure from occurring, two elements must be considered: the oscillations between the bus voltage and earth and the PWM frequency. If both elements above do not enter into resonance with the motor, then there is no risk for the motor.

When selecting power supply, please check the conditions below:

Peak voltages and dv/dt gradients generated by the power supply must not exceed the values below:

- 300 VDC controllers: 750 (phase to phase, phase to ground, neutral to ground), voltage gradient: 8kv/us. as shown Table2.2.1.1 and Figure2.2.1.1
- 600 or 750 VDC controllers: 1050 VP maximum (phase to phase, phase to ground, neutral to ground at the PWM frequency) and a voltage gradient: 11kv/us as shown Table2.2.1.2 and Figure2.2.1.2

The cable between the controller and the motor will generate reflected waves due to the impedance mismatch between the cable and the motor. The reflected voltage will be superimposed on the subsequent input voltage, causing the voltage to rise. This phenomenon will be more obvious when the motor cable is longer. If the cable length between the controller and the motor exceeds 10 meters, it is necessary to measure and ensure that the voltage at the motor terminal is lower than the above regulations. If the measured value is outside the specification, a dV/dt filter must be inserted between the controller and the motor for protection.

For a detailed description of this voltage oscillation phenomenon, please refer to Sections 2.2.2 and 2.2.3.

Table2.2.1.1 LMC, LMT series voltage limitation of power supply and neutral point

Item	330 V_{DC} Controllers
V_{bus}	Max. 330
$ V_{peak. to ground}^+ $	< 750 V_p (phase to ground) @ PWM frequency
$ V_{peak. to ground}^- $	< 750 V_p (phase to ground) @ PWM frequency
Voltage gradient $ dV/dt $	< 8kV/ μ s (instantaneous) If it is difficult to obtain instantaneous voltage gradient, the following formula can be used to estimate (Figure2.2.1.1) : $ dV/dt = (90\%V_{pp} - 10\%V_p)/t_r $




Figure2.2.1.1 Voltage oscillation schematic (300 V_{DC} controller),

Table2.2.1.2 LMS, LMSA, LMF, LMFA, LMFP series voltage limitation of power supply and neutral point

Item	LMSA, LMF, LMFA, LMFP	LMS
V_{bus}	Max. 750	Max. 600
$ V_{peak. to ground}^+ $	< 1050 V_p (phase to ground) @ PWM frequency	
$ V_{peak. to ground}^- $	< 1050 V_p (phase to ground) @ PWM frequency	
Voltage gradient $ dV/dt $	< 11kV/ μ s (instantaneous) If it is difficult to obtain instantaneous voltage gradient, the following formula can be used to estimate (Figure2.2.1.1) : $ dV/dt = (90\%V_{pp} - 10\%V_p)/t_r $	


Figure2.2.1.2 Voltage oscillation schematic (600/750 V_{DC} controller)

2.2.2 Cable line voltage reflection phenomenon

When electromagnetic waves are transmitted in a conductor, there will actually be changes in voltage and current along the conductor. When the length of the line is very short relative to the wavelength, this phenomenon can be ignored and the entire line can be regarded as the same voltage. However, when the frequency of the electromagnetic wave is high enough, the wavelength will become very short. In this case, the voltage will have a clear distribution in the cable, and the voltage distribution of the conductor must be calculated using transmission line theory. In transmission line theory, electricity is viewed as an electromagnetic wave transmitted in a cable. Impedance mismatch during transmission will lead to incident reflection. This phenomenon is more likely to occur when using a motor because the impedance of the motor is relatively larger than that of the cable, which in turn generates a reflected voltage that is superimposed on the incident voltage waveform.

This phenomenon is affected by the rise time of the voltage signal. According to IEC61800-8, the common rise time t_r is 50ns to 1μs (defined in Figure 2.2.2.1). After calculating the transmission wave velocity v based on the characteristic inductance and characteristic capacitance of the cable, the limit length l_{cr} at which the maximum reflected voltage will be generated can be estimated:

$$v = \frac{1}{\sqrt{L_0 C_0}} \text{ (Typically } 50 \sim 300 \text{ m}/\mu\text{s)}$$

$$l_{cr} = \frac{v t_r}{2}$$

v = Transmission wave speed of the cable

L_0 = Cable characteristic inductance

C_0 = Cable characteristic capacitance




Figure 2.2.2.1 Rising time t_r definition

2.3 Cooling related

2.3.1 Cooling system calculation

WARNING

Risk of working temperature.

When incorrectly operated and in the case of a fault, the motor can overheat resulting in fire and smoke. This can result in severe injury or death. Further, excessively high temperatures destroy motor components and result in increased failures as well as shorter service lives of motors.



- ◆ Operate the motor according to the relevant specifications.
- ◆ Allow the forcer to cool down sufficiently (in a 25°C room temperature) before working around the product to avoid burns.
- ◆ The motor coil will achieve maximum working temperature 120°C.
- ◆ When an abnormal smell, noise, smoke, or vibration is detected, please turn off the power immediately.

The motor cooling system mainly utilizes the motor maximum dissipated heat output, minimum flow rate of coolant, pressure difference between coolant inlet and an outlet and the temperature difference between the coolant inlet and outlet for calculation. During operation, performing design and selection of a cooling system according to the catalog value is able to allow the motor to achieve optimal performance. If the equivalent thrust force of the motor actual operation is lower than the continuous force indicated in the catalog, under the condition where the motor is permitted to operate at a higher temperature (but not exceeding the maximum winding temperature of 120°C), its coolant flow rate may be reduced lower to prevent excessive consumption of pumping work. The cooling condition can be adjusted appropriately according to the following formula.

The following formula can be used to adjust the water-cooling system boundary condition according to different motor power losses: Under the user's operational condition where the equivalent thrust force is smaller than the Continuous force ($F_e < F_c$), to determine the coolant flow rate required to be adjusted at the customer end, the following equation can be used to solve the coolant flow rate corresponding to the equivalent thrust force.

$$Q_{P,H,e} = \frac{Q_{P,H,MAX}}{(F_c/F_e)^2}$$

$$Q_{P,H,e} = 69.7 \times q_e \times \Delta T$$

where

$Q_{P,H,e}$: Motor total loss under the equivalent thrust force [W]

$Q_{P,H,MAX}$: Maximum dissipated heat output [W]

ΔT : Temperature difference between inlet and outlet [°C]

q_e : Coolant flow rate under the equivalent thrust force [L/min]

F_c : Continuous force (catalog value) [N]

F_e : Equivalent thrust force of actual operation [N]

The relationship between the coolant flow rate and the temperature difference of inlet and outlet is as shown in figure2.3.1.1, and the relationship between the pressure difference of inlet and outlet and the flow rate is as shown in figure2.3.1.2.




Figure 2.3.1.1 Coolant flow rate and temperature difference of inlet and outlet relationship graph




Figure 2.3.1.2 Pressure difference of inlet and outlet and flow rate relationship graph

2.3.2 Cooling machine selection

For the selection of a cooling machine, in addition to the consideration of the use scope of the power source and coolant, it mainly refers to the selection of the cooling power and flow rate. It is recommended to select a cooling machine capable of allowing the motor to achieve maximum performance according to the catalog value, or the calculation value of the cooling system described in section 2.3.1 can be used as a reference for the selection.

2.3.3 Cooling power selection

The following provides an example. If two linear motors of LMFA31 are used, and the **maximum dissipated heat output** indicated in the catalog specification is 324 (W), then the sum of the maximum dissipated heat output of the two motors is $2 \times 324 = 648$ (W). By using the cooling machine of than the motor maximum dissipated heat output of 648 (W) as an example, under 50Hz, the cooling capacity is 980 (W), which is greater.

Table 2.3.3.1 LMFA31 series specification

LMFA3 series specification	Symbol	Unit	LMFA31	LMFA31L
Continuous force	F_c	N	380	380
Continuous Current	I_c	A(rms)	3.1	4.6
Continuous force (WC)	$F_c(wc)$	N	759	759
Continuous current (WC)	$I_c(wc)$	A(rms)	6.2	9.1
Peak force (1 second)	F_p	N	1750	1750
Peak current (1 second)	I_p	A(rms)	19.2	28.3
Force constant	K_f	N/A(rms)	122.7	83.1
Attraction force	F_a	N	3430	3430
Maximum winding temperature	T_{max}	°C	120°C	
Electrical time constant	K_e	ms	11.3	11.4
Resistance (line-to-line, 25°C)	R_{25}	Ω	4.3	1.9
Resistance (line-to-line, 120°C)	R_{120}	Ω	5.6	2.6
Inductance (line-to-line)	L	mH	48.3	22.2
Pole pair distance	2τ	mm	46	
Back EMF constant (line-to-line)	K_v	Vrms(m/s)	70.9	48.0
Motor constant (25°C)	K_m	N/√W	48.4	48.7
Thermal resistance	R_{th}	°C/W	1.17	1.19
Thermal resistance (WC)	$R_{th}(wc)$	°C/W	0.29	0.30
Minimum flow rate	-	L/min	4.0	4.0
Temperature of cooling water	-	°C	20	
Thermal sensor switch	-		1xKTY84-130+1x(3PTC SNM120 In Series)	
Maximum speed of Peak force	V_{max}, F_{max}	m/s	4.08	6.19
Maximum output power	PEL, MAX	W	10255	13910
Maximum dissipated heat output	$Q_{P,H,MAX}$	W	324	320
Locked-rotor torque (water-cooling)	F_e	N	531	531
Stall current (water-cooling)	I_0	A(rms)	4.3	6.4

Table 2.3.3.2 Cooling machine power selection

Item/Model		HWK- 50PTS	HWK- 250PTS	HWK- 400PTS	HWK- 600PTS	HWK- 750PTS	HWK- 900PTS
Cooling capacity	KCAL/H 50/60Hz	450/500	840/1000	1400/1500	1700/2100	2600/3000	3200/3800
	W 50/60Hz	525/580	980/1170	1630/1750	1980/2450	2900/3500	3700/4400
	BTU/H 50/60Hz	1800/2000	3360/4000	5600/6000	6800/8400	10000/12000	12800/15200
Temperature control	A	Fixed type (setting range of 10~40℃)					
	B	Temperature difference type (room temperature/machine body temperature tracking type, setting range of -10 ~ +10℃)					
Scope of use	Room temperature	10 ~ 40℃					
	Oil temperature	10 ~ 30℃					
Power		3φ200~230V 50/60Hz					
Motor (W)	Compressor	460			740	1135	1450
	Fan	56	50	95		180	
	Pump	120	750				
Pump flow (L/min)	50Hz	2	40				
	60Hz	3.5	50				

2.3.4 Flow rate selection

When the cooling machine is under the selected frequency (50/60Hz), the pump flow rate shall be greater than the sum of the motor minimum flow rate, and the pressure generated by the pump flow rate shall be greater than the sum of the pressure drop of the motor internal cooling loop. If the cooling loop of large equipment is longer, then it is necessary to consider the pressure drop caused by the loop pipe resistance.

The following provides an example. If two linear motors of LMFA31 are used, and the **minimum flow rate** indicated in the catalog specification is 4.0 (L/min), then the sum of the minimum flow rate of the two motors is $2 \times 4.0 = 8.0$ (L/min). By using the cooling machine of table 2.3.4.2 as an example, the pump flow rate at 50 Hz is 40 (L/min), which is greater than the motor minimum flow rate of 8.0 (L/min).

Table 2.3.4.1 LMFA31 series specification

LMFA3 series specification	Symbol	Unit	LMFA31	LMFA31L
Continuous force	Fc	N	380	380
Continuous Current	Ic	A(rms)	3.1	4.6
Continuous force (WC)	Fc(wc)	N	759	759
Continuous current (WC)	Ic(wc)	A(rms)	6.2	9.1
Peak force (1 second)	Fp	N	1750	1750
Peak current (1 second)	Ip	A(rms)	19.2	28.3
Force constant	Kf	N/A(rms)	122.7	83.1
Attraction force	Fa	N	3430	3430
Maximum winding temperature	Tmax	°C	120°C	
Electrical time constant	Ke	ms	11.3	11.4
Resistance (line-to-line, 25°C)	R ₂₅	Ω	4.3	1.9
Resistance (line-to-line, 120°C)	R ₁₂₀	Ω	5.6	2.6
Inductance (line-to-line)	L	mH	48.3	22.2
Pole pair distance	2 τ	mm	46	
Back EMF constant (line-to-line)	Kv	Vrms(m/s)	70.9	48.0
Motor constant (25°C)	Km	N/√W	48.4	48.7
Thermal resistance	Rth	°C/W	1.17	1.19
Thermal resistance (WC)	Rth(wc)	°C/W	0.29	0.30
Minimum flow rate	-	L/min	4.0	4.0
Temperature of cooling water	-	°C	20	
Thermal sensor switch	-		1xKTY84-130+1x(3PTC SNM120 In Series)	
Maximum speed of Peak force	Vmax,Fmax	m/s	4.08	6.19
Maximum output power	PEL,MAX	W	10255	13910
Maximum dissipated heat output	Q _{P,H,MAX}	W	324	320
Locked-rotor torque (water-cooling)	Fe	N	531	531
Stall current (water-cooling)	I0	A(rms)	4.3	6.4

Table 2.3.4.2 Cooling machine flow rate selection

Item/Model		HWK- 50PTS	HWK- 250PTS	HWK- 400PTS	HWK- 600PTS	HWK- 750PTS	HWK- 900PTS
Cooling capacity	KCAL/H 50/60Hz	450/500	840/1000	1400/1500	1700/2100	2600/3000	3200/3800
	W 50/60Hz	525/580	980/1170	1630/1750	1980/2450	2900/3500	3700/4400
	BTU/H 50/60Hz	1800/2000	3360/4000	5600/6000	6800/8400	10000/12000	12800/15200
Temperature control	A	Fixed type (setting range of 10~40℃)					
	B	Temperature difference type (room temperature/machine body temperature tracking type, setting range of -10 ~ +10℃)					
Scope of use	Room temperature	10 ~ 40℃					
	Oil temperature	10 ~ 30℃					
Power		3φ200~230V 50/60Hz					
Motor (W)	Compressor	460			740	1135	1450
	Fan	56	50	95		180	
	Pump	120	750				
Pump flow (L/min)	50Hz	2	40				
	60Hz	3.5	50				

The above briefly describes the selection of a cooling machine. For any questions on the selection of a cooling machine, it is recommended to provide the above information to a cooling machine manufacturer for further discussion.

3. Interface Design

3.	Interface Design	3-1
3.1	Interface design	3-3
3.1.1	Water cooling design	3-3
3.1.1.1	LMFA/LMFP Water-cooling motor cooling tube design	3-3
3.1.1.2	LMFA/LMFP water-cooling motor with LMFC precision water-cooling channel design	3-4
3.1.1.3	Material used in water-cooling channel	3-8
3.1.1.4	Coolant of water-cooling linear motor	3-8
3.1.2	Iron core linear motor assembly interface	3-10
3.1.2.1	LMSA iron core linear motor series	3-11
3.1.2.2	LMFA water-cooling linear motor series	3-12
3.1.2.3	LMSC double thrust linear motor series	3-15
3.1.2.4	LMSS iron core linear motor series	3-16
3.1.2.5	LME iron core linear motor series	3-17
3.1.3	Ironless linear motor (LMC) mechanical installation interface	3-18
3.1.4	Tubular linear motor (LMT) mechanical installation interface	3-19
3.2	Mounting	3-23
3.2.1	Force vs. air gap	3-23
3.2.1.1	LMSA Series	3-24
3.2.1.2	LMFA series	3-26
3.2.1.3	LMFP series	3-32
3.2.1.4	LMSC series	3-38
3.2.1.5	LME seires	3-39
3.2.2	Screw selection rules and instructions	3-43
3.2.2.1	Force and stator screw installation hole specification table	3-44
3.2.2.2	Forcer recommended screw fastening depth table	3-47
3.2.2.3	Stator recommended screw fastening minimum depth table	3-48
3.2.2.4	Forcer and stator recommended screw torque table	3-48
3.3	Electrical connection	3-49
3.3.1	Cable	3-49
3.3.1.1	Standard specification of power cable	3-49
3.3.1.2	Recommended construction method for grounding protection	3-49
3.3.1.3	Recommended construction method for ironless linear motor grounding protection	3-50
3.3.1.4	Recommended installation method of extension cable for LMSA-Z series	3-51
3.3.1.5	Motor with connector series	3-58
3.3.1.6	Connector selection and pin assignment	3-60
3.3.2	Forcer parallel design	3-64

3.3.2.1	Linear motor moving direction	3-65
3.3.2.2	LMSA/LMSA-Z/LME linear motor series	3-66
3.3.2.3	LMFA water-cooling linear motor series	3-67
3.3.2.4	LMSC magnetic brake linear motor series	3-68
3.3.2.5	LMSS linear motor series	3-69
3.3.2.6	LMC ironless linear motor series	3-70
3.3.2.7	LMT Tubular linear motor series	3-74
3.3.3	Hall accessories	3-77
3.3.3.1	Hall sensor	3-77
3.3.3.2	Hall sensor installation instructions	3-83
3.3.3.3	Selection of Hall sensor screws	3-84
3.3.3.4	Hall encoder	3-85
3.3.3.5	Hall encoder coding instructions	3-86
3.3.3.6	Hall encoder characteristic specification	3-87
3.3.3.7	Hall encoder dimension	3-88

3.1 Interface design

3.1.1 Water cooling design

3.1.1.1 LMFA/LMFP Water-cooling motor cooling tube design

When a multiple number of linear motors are used, the cooling tubes of the motor must be installed in the parallel method, as shown in figure 3.1.1.1.1 (the inlet at the left side of the motor is connected to the inlet at the right side of the motor, and the outlets are also connected in the same way). When precision water-cooling is used, the channel is as shown in figure 3.1.1.1.2. For multiple precision water-cooling channels, please refer to figure 3.1.1.1.3.

Recommendation: Separate the channels of the forcer precision water-cooling and the stator precision water-cooling for operation can achieve greater effect.




Figure 3.1.1.1.1 Motor cooling tube installation illustration




Figure 3.1.1.1.2 Precision water-cooling channel illustration




Figure 3.1.1.1.3 Multiple precision water-cooling channels illustration

3.1.1.2 LMFA/LMFP water-cooling motor with LMFC precision water-cooling channel design

During the use of the water-cooling linear motor LMFA/LMFP along with the precision water-cooling series LMFC, the motor characteristic indicated on the HIWIN water-cooling motor drawings and specification refers to the water-cooling condition, and the coolant temperature is 20°C. The water-cooling motor can also use oil cooling, and at this time, the motor performance may be adjusted appropriately according to the characteristic of the coolant. The cooling condition indicated in the motor specification refers to the continuous running condition when the motor stator is under the criteria of continuous force, thereby ensuring the coil temperature is controlled under the minimum criteria of below 120°C. The performance of LMFC precision water-cooling is defined to be that the precision water-cooling surface temperature shall not be higher than the cooling machine outlet temperature setting by more than 4°C. LMFC stator precision water-cooling includes the following two types, and the LMFC3~6 series adopts the standard type water channel design, as shown in figure 3.1.1.2.1. LMFC3~4 series adopts the return flow type water channel design, as shown in figure 3.1.1.2.2.




Figure 3.1.1.2.1 Standard type water channel illustration




Figure 3.1.1.2.2 Return flow type water-cooling channel illustration




Figure 3.1.1.2.3 Standard type installation interface




Figure 3.1.1.2.4 Return flow type installation interface

Table 3.1.1.2.1 Return flow type Installation dimension chart

Model	Dimensions (mm)
	W
LMFC3□	50
LMFC4□	100

LMFC Precision water-cooling linear motor assembly illustration is as shown in the drawing below




Figure 3.1.1.2.5 LMFA precision water-cooling linear motor assembly illustration

Table 3.1.1.2.2 LMFA precision water-cooling installation dimension

Model	Dimensions (mm)				
	L	L1	L2	L3	L4
LMFC0□					
LMFC1□					
LMFC2□					
LMFC3□	150	131	126.5	30	155
LMFC4□	197	178	173.5	30	201
LMFC5□	257	236	231.5	124	251
LMFC6□	351	330	325.5	171	345




Figure 3.1.1.2.6 LMFP precision water-cooling linear motor assembly illustration

Table 3.1.1.2.3 LMFP precision water-cooling installation dimension

Model	Dimensions (mm)				
	L	L1	L2	L3	L4
LMFC0□					
LMFC1□					
LMFC2□					
LMFC3□	150	133	128.5	53.5	155
LMFC4□	197	180	175.5	53.5	201
LMFC5□	257	240	235.5	53.5	251
LMFC6□	351	334	329.5	53.5	345

3.1.1.3 Material used in water-cooling channel

Table 3.1.1.3.1 Water-cooling channel material chart

Item	Material
LMFA water-cooling linear motor	Cu (SF-Cu), SUS303 (1.4305), Viton
LMFC forcer precision water-cooling	A6061 (AlMgSi0.5), SUS304 (1.4301), Viton
LMFC stator precision water-cooling	A6061 (AlMgSi0.5), SUS303 (1.4305), Viton

3.1.1.4 Coolant of water-cooling linear motor

CAUTION



Risk of working temperature.

Beware the operating environment of the cooling system to avoid damage.

- ◆ Please do not use the cooling system in frosty or icy environment.
- ◆ Please do not use untreated water, or it might cause serious damage or break down.

Customer could decide which cooling system and coolant to use with below requirements.

- It is recommended to use anti-corrosion water as the coolant.
- The cooling medium must be cleaned or filtered in advance to prevent blockage of the cooling circuit.
- The maximum allowable size of particles in the cooling medium is 100µm.
- Coolant must be compatible with O-ring material to avoid pollution.
- Recommended additive including.
 - (1). Ethylene glycol (thermosensitivity)
 - (2). Ethylene glycol with 20%-30% softened water

- (3). Water with 3% Panolin
- (4). Water with 10%-20% Tyfocor
- (5). Oil with 7 cst viscosity
- (6). Water with 30% Clysantin

Water which is used as basis for the coolant must comply as a minimum with the following requirements.

- (1). Chloride concentration: $c < 100 \text{ mg/l}$
- (2). Sulfate concentration: $c < 100 \text{ mg/l}$
- (3). $6.5 \leq \text{PH value} \leq 9.5$

Contact the anti-corrosion agent manufacturer relating to additional requirements!

3.1.2 Iron core linear motor assembly interface

Observe dimension of the gap between forcer and stator after assembly. It will impact linear motor performance and reliability. A well-designed positioning stage and proper tolerance value will improve the stability of products. The sectional view of typical linear motor stage base and the suggested tolerance value are shown as below. The flatness of the installation interface with stator should be 0.1mm per 500mm (as figure 3.1.2.1 shows).




Figure 3.1.2.1 Sectional view of base design

Observe the assembly total height H and the air gap dimensions between the forcer and stator G after assembly, they will impact the linear motor performance and reliability (please refer to the air gap specification of each series motor). There are two types of stators: stainless cover version and epoxy version.

Forcer and stator of an iron-core linear motor have an immense magnetic attraction with each other (refer to linear motor catalog F_a of each series for the attraction value). Hence, when designing the installation interfaces of both forcer and stator, we must consider and compute the deformation due to the attraction to ensure the height of the total composition H and air gap between the forcer and stator G can be maintained. Should there be any circumstance of a bad air gap G caused by structural deformation, or interferential damage of forcer and stator, HIWIN shall not be responsible for repairs or adjustments free of charge.

3.1.2.1 LMSA iron core linear motor series




Figure 3.1.2.1.1 LMSA iron core linear motor assembly

Table 3.1.2.1.1 LMSA/LMSA-Z iron core linear motor assembly dimensions

Model	Dimensions (mm)							
	H1	K1		L1		G1		S1
		Cover	Epoxy	Digital	Analog	Stainless cover	Epoxy	Stainless cover/Epoxy
LMSA0□ LMSA0□-Z	34	4.2	3.5			0.6 +0.35/-0.25	0.6 ±0.25	
LMSA1□ LMSA1□-Z	34	5.7	5	28	42.6			1 ±0.2
LMSA2□ LMSA2□-Z	34	3.7	3	28	42.6			
LMSA3□ LMSA3□-Z	36	3.7	3	28	42.6			
LMSAC□	36	1.75		28	42.6			

Note: S1 is the gap between Hall sensor and stator after motor assembly.

3.1.2.2 LMFA water-cooling linear motor series

Note:

- (1). The precision water-cooling installation dimensions are not included.
- (2). When measure the width of forcer, since the epoxy could expand or contract with temperature changes, as below pictures




Figure 3.1.2.2.1 LMFA water-cooling linear motor assembly




Figure 3.1.2.2.2 LMFP water-cooling linear motor assembly

Table 3.1.2.2.1 LMFA/LMFP water-cooling linear motor assembly dimensions

Model	Dimensions (mm)						
	H2	L2		G2		S2	
		Digital	Analog	Stainless cover	Epoxy	Stainless cover	Epoxy
LMFA0□	48.5	26.4	57	0.9±0.2	1.4±0.2	1.1±0.2	1.4±0.2
LMFA1□	48.5	26.4	57				
LMFA2□/LMFP24	50.5	26.4	57				
LMFA3□/LMFP3□	64.1	33	34.9				
LMFA4□/LMFP4□	66.1	33	34.9				
LMFA5□/LMFP5□	64.1	33	34.9				
LMFA6□/LMFP6□	66.1	33	34.9				

Note: S2 is the gap between Hall sensor and stator after motor assembly.

Note: The LMFC precision water-cooling installation dimensions are included.




Figure 3.1.2.2.3 LMFA precision water-cooling linear motor assembly




Figure 3.1.2.2.4 LMFP precision water-cooling linear motor assembly

Table 3.1.2.2.2 LMFA/LMFP precision water-cooling linear motor assembly dimensions

Model	Dimensions (mm)								
	H3	H3a	H3b	L3		G3		S3	
				Digital	Analog	Stainless cover	Epoxy	Stainless cover	Epoxy
LMFA0□				26.4	57			1.1±0.2	1.4±0.2
LMFA1□				26.4	57				
LMFA2□/LMFP24				26.4	57				
LMFA3□/LMFP3□	79.0	76	67.1	33	34.9	0.9±0.5	1.4±0.5		
LMFA4□/LMFP4□	81.0	78	69.1	33	34.9				
LMFA5□/LMFP5□	86.0	76	74.1	33	34.9				
LMFA6□/LMFP6□	88.0	78	76.1	33	34.9				

Note:

- (1). H3 : Contain forcer, stator, precision cooling device system for the forcer and stator.
- (2). H3a : Contain forcer, stator and precision cooling device system for forcer.
- (3). H3b : Contain forcer, stator and precision cooling device system for stator.
- (4). S3 is the gap between Hall sensor and stator after motor assembly.

3.1.2.3 LMSC double thrust linear motor series




Figure 3.1.2.3.1 LMSC double thrust linear motor assembly

Table 3.1.2.3.1 LMSC double thrust linear motor assembly dimensions

Model	Dimensions (mm)	
	H4	G4
LMSC7	131.5	0.75 +0.35/-0.2

3.1.2.4 LMSS iron core linear motor series




Figure 3.1.2.4.1 LMSS iron core linear motor assembly

Table 3.1.2.4.1 LMSS iron core linear motor assembly dimensions

Model	Dimensions (mm)		
	H5	K2	G5
LMSS11	34.3	3	0.9 +0.3/-0.35

3.1.2.5 LME iron core linear motor series




Figure 3.1.2.5.1 LME iron core linear motor assembly

Table 3.1.2.5.1 LME iron core linear motor assembly dimensions

Model	Dimensions (mm)		
	H6	K6	G6
		Cover	Stainless cover
LME-A-12	40	5.7	0.6 +0.35/-0.25
LME-A-22(L)			
LME-B-13			
LME-B-22			
LME-B-23(L)			

3.1.3 Ironless linear motor (LMC) mechanical installation interface

For the installation surface (datum plane A) of a ironless linear motor fastened with a stator assembly, the recommended plane precision is 0.02mm/300mm; for the installation plane fastening with a forcer assembly, the recommended plane precision is 0.02mm/300mm, and it is parallel to the datum plane A, and the parallel precision is 0.02mm/300mm.




Figure 3.1.3.1 Ironless linear motor installation interface assembly precision

When a ironless linear motor is installed with the forcer and stator assembly, please pay special attention to the dimensions (H & G1 & G2 & G3) between the forcer and stator, and such dimensions can affect the performance and reliability of the linear motor. (For values H & G1 & G2 & G3, please refer to table 3.1.3.1)




Figure 3.1.3.2 Ironless linear motor installation dimension

Table 3.1.3.1 Ironless linear motor installation dimension chart

Model	Dimension (mm)			
	H	G1	G2	G3
LMCA	74.5	≥ 0.4	1	1
LMCB	94.5	≥ 0.4	1	1
LMCC	117.5	≥ 0.4	1	3
LMCD	105	≥ 0.4	1.2	1
LMCE	125	≥ 0.4	1.2	1
LMCF	172	≥ 0.4	1.2	2.3
LMC-EFC	68.5	≥ 0.4	1.3	0.35
LMC-EFE	93	≥ 0.4	1.3	0.35
LMC-EFF	122	≥ 0.4	1.4	0.5
LMC-HUB	53	≥ 0.4	0.5	0.65

3.1.4 Tubular linear motor (LMT) mechanical installation interface

For the fixation base installation surface (datum plane A) secured underneath the stator assembly, the recommended plane precision is 0.02mm/300mm. For the installation surface fastening theforcer assembly, the recommended plane precision is 0.02mm/300mm, and it is parallel to the datum plane A, and the parallel precision is 0.02mm/300mm.




Figure 3.1.4.1 tubular linear motor installation interface geometric precision

The recommended design of stator fixation base is to use a V-shape sleeper.




Figure 3.1.4.2 Fixation base design

The fixation base length (L1) for securing the stator can be changed for different strokes.

Table 3.1.4.1 Securement length of fixation base

Model	LMT2D/LMT2T/LMT2Q		
Stroke S (mm)	50~350	400~800	850~1050
L1 (mm)	25	40	60
Model	LMT6D/LMT6T/LMT6Q		
Stroke S (mm)	100~350	400~800	850~1050
L1 (mm)	25	40	60
Model	LMTA2/LMTA3/LMTA4		
Stroke S (mm)	100~300	350~700	750~1550
L1 (mm)	25	40	60
Model	LMTB2/LMTB3/LMTB4		
Stroke S (mm)	100~700	750~1300	1350~1550
L1 (mm)	50	70	100
Model	LMTC2/LMTC3/LMTC4		
Stroke S (mm)	100~750	800~1500	1550~2000
L1 (mm)	50	70	100

Both H1 and H2 refer to the dimension of height from the datum plane A to the stator assembly center. It is recommended that after the installation of the stator assembly, the height difference shall not exceed 0.2mm; both W1 and W2 refer to the dimension of height from the datum plane B to the stator assembly center. It is recommended that after the installation of the stator assembly, the height difference shall not exceed 0.2mm; $|H1-H2| \leq 0.2\text{mm}$; $|W1-W2| \leq 0.2\text{mm}$. (as shown in figure 3.1.4.3)




Figure 3.1.4.3 Stator assembly installation dimension

Datum C refers to the center of a stator assembly, and datum D refers to the reference axis of a forcer assembly. It is recommended that after the installation of the forcer and stator assemblies, the concentricity of datum C and datum D shall not be greater than 0.2mm. (as shown in figure 3.1.4.4)




Figure 3.1.4.4 Geometric tolerance of forcer and stator assembly installation height

During the installation of the forcer and stator assembly, please pay special attention to the dimension (G) between the forcer and stator, and such dimensions can affect the performance and reliability of the linear motor (as shown in figure 3.1.4.5). (The values of G, $\Phi D1$ are as shown in table 3.1.4.2).




Figure 3.1.4.5 Forcer and stator installation dimensions precision

Table 3.1.4.2 Installation dimensions

Model	Dimensions (mm)	
	øD1	G
LMT2	13	0.25~0.50
LMT6	16	0.25~0.50
LMTA	21.5	0.375~0.75
LMTB	26.5	0.375~0.75
LMTC	37	0.50~1.00

The guideway is magnetic element which could easily generate attraction force with the stator. In order to avoid the stator be deformed by the attraction force and problems in installation, please keep the installation distance(c) as shown in figure 3.1.4.6 and table 3.1.4.3.




Figure 3.1.4.6 Installation distance while installing guideway

Table 3.1.4.3 Installation distance

Series	LMT2	LMT6	LMTA	LMTB	LMTC
c(mm)	≥ 30	≥ 30	≥ 40	≥ 50	≥ 80

The installation distance(d) as shown in figure 3.1.4.7 and table 3.1.4.4 should be kept as well while installing the magnetic scale, or it will easily cause interference in positioning if the magnetic field is too strong.




Figure 3.1.4.7 Installation distance while installing magnetic scale

Table 3.1.4.4 Installation distance

Series	LMT2	LMT6	LMTA	LMTB	LMTC
d(mm)	≥ 40	≥ 50	≥ 60	≥ 70	≥ 100

3.2 Mounting

3.2.1 Force vs. air gap

The linear motor continuous force/peak force and the attraction force between the forcer and stator change along with the assembly air gap between the forcer and stator. In this chapter, the relationship between the Continuous force/peak force, attraction force and assembly air gap of each series motor is described in order to provide such information as reference for motor selection and mechanical design.

3.2.1.1 LMSA Series

■ Continuous force/peak force and air gap




Figure 3.2.1.1.1 LMSA Continuous force/peak force-air gap relationship graph

Table 3.2.1.1.1 LMSA Continuous force/peak force-air gap comparison chart

Series	LMSA□□/ LMSA□□-Z									
Air gap (mm)	0.1	0.2	0.3	0.4	0.5	0.6	0.7	0.8	0.9	1.0
Force (%)	114	111	108	105	103	100	98	95	93	90

■ Attraction force and air gap




Figure 3.2.1.1.2 LMSA attraction force-air gap relationship graph

Table 3.2.1.1.2 LMSA attraction force-air gap comparison chart

LMSA0□~LMSA2□ / LMSA0□-Z ~LMSA2□-Z series attraction force. Unit: N									
Air gap (mm)	LMSA01 LMSA01-Z	LMSA02 LMSA02-Z	LMSA11 LMSA11-Z	LMSA12 LMSA12-Z	LMSA13 LMSA13-Z	LMSA21 LMSA21-Z	LMSA22 LMSA22-Z	LMSA23 LMSA23-Z	LMSA24 LMSA24-Z
0	327	653	653	1306	1959	1306	2612	3918	5224
0.3	280	560	560	1120	1680	1120	2240	3360	4480
0.6	241	481	481	963	1444	963	1926	2888	3851
0.9	208	415	415	830	1245	830	1660	2490	3320
1.2	180	359	359	718	1077	718	1436	2154	2872
1.5	156	312	312	624	936	624	1248	1872	2496
1.8	136	271	271	542	813	542	1084	1626	2168
2.1	118	236	236	472	708	472	944	1416	1888
5	33	66	66	132	198	132	264	396	528
10	4	8	8	16	24	16	32	48	64
15	0.5	1	1	2	3	2	4	6	8
LMSA3□ ~LMSAC□/ LMSA3□-Z series attraction force. Unit: N									
Air gap (mm)	LMSA31 LMSA31-Z	LMSA32 LMSA32-Z	LMSA33 LMSA33-Z	LMSA34 LMSA34-Z	LMSAC3	LMSAC5			
0	1959	3918	5877	7836	6367	10611			
0.3	1680	3360	5040	6720	5460	9100			
0.6	1444	2888	4333	5777	4694	7823			
0.9	1245	2490	3735	4980	4046	6744			
1.2	1077	2154	3231	4308	3500	5834			
1.5	936	1872	2808	3744	3042	5070			
1.8	813	1626	2439	3252	2642	4404			
2.1	708	1416	2124	2832	2301	3835			
5	198	396	594	792	644	1073			
10	24	48	72	96	78	130			
15	3	6	9	12	10	16			

3.2.1.2 LMFA series

■ Continuous force/peak force and air gap: Cover type




Figure 3.2.1.2.1 LMFA with cover type continuous force/peak force-air gap relationship graph

Table 3.2.1.2.1 LMFA with cover type continuous force/peak force-air gap comparison chart

LMFA series continuous force/peak force (Cover type). Unit: %		
Air gap (mm)	LMFA0~LMFA2	LMFA3~LMFA6
0.1	119	117
0.2	117	114
0.3	114	113
0.4	112	111
0.5	110	109
0.6	107	106
0.7	105	104
0.8	103	102
0.9	100	100
1	98	99
1.1	96	97
1.2	94	95
1.3	92	93
1.4	90	92
1.5	88	90
1.6	86	88
1.7	84	86
1.8	82	85

■ Continuous force/peak force and air gap: Epoxy type




Figure 3.2.1.2.2 LMFA with epoxy type Continuous force/peak force-air gap relationship graph

Table 3.2.1.2.2 LMFA with epoxy type Continuous force/peak force-air gap comparison chart

LMFA series continuous force/peak force (Epoxy type). Unit: %		
Air gap (mm)	LMFA0~LMFA2	LMFA3~LMFA6
0.1	131	127
0.2	129	124
0.3	127	123
0.4	124	120
0.5	121	118
0.6	119	116
0.7	116	114
0.8	114	112
0.9	112	110
1	109	108
1.1	107	106
1.2	104	103
1.3	102	102
1.4	100	100
1.5	98	98
1.6	96	96
1.7	94	95
1.8	92	93

■ Attraction force and air gap: Cover type




Figure 3.2.1.2.3 LMFA with cover type attraction force-air gap relationship graph

Table 3.2.1.2.3 LMFA0~2 with cover type attraction force-air gap comparison chart

LMFA0~LMFA2 series attraction force (Cover type). Unit: N											
Air gap (mm)	LMFA01	LMFA02	LMFA03	LMFA11	LMFA12	LMFA13	LMFA14	LMFA21	LMFA22	LMFA23	LMFA24
0	713	1426	2141	1306	2612	3919	5225	1965	3930	5894	7859
0.45	569	1138	1709	1042	2085	3127	4169	1568	3136	4704	6271
0.9	457	914	1372	837	1674	2511	3348	1259	2518	3777	5036
1.35	369	738	1108	676	1352	2029	2705	1017	2034	3051	4068
1.8	299	599	899	548	1097	1645	2194	825	1650	2475	3299
2.25	244	487	731	446	892	1338	1785	671	1342	2013	2684
2.7	199	398	597	364	729	1093	1458	548	1097	1645	2193
3.15	163	325	488	298	595	893	1191	448	896	1343	1791
5	72	145	218	133	266	398	531	200	399	599	799
10	9	17	26	16	32	48	64	24	48	72	96
15	1	3	4	2	5	7	10	4	7	11	15
20	0	0	1	0	1	1	2	1	1	2	2

Table 3.2.1.2.4 LMFA3~6 with cover type attraction force-air gap comparison chart

LMFA3□~LMFA4□ series attraction force (Cover type). Unit: N								
Air gap (mm)	LMFA31	LMFA32	LMFA33	LMFA34	LMFA41	LMFA42	LMFA43	LMFA44
0	4926	9851	14777	19703	7388	14777	22165	29554
0.45	4089	8179	12268	16357	6134	12268	18402	24536
0.9	3430	6860	10290	13720	5145	10290	15435	20580
1.35	2902	5805	8707	11609	4354	8707	13061	17414
1.8	2471	4942	7413	9884	3707	7413	11120	14826
2.25	2117	4234	6351	8468	3176	6351	9527	12703
2.7	1821	3642	5462	7283	2731	5462	8193	10925
3.15	1572	3144	4717	6289	2358	4717	7075	9433
5	885	1770	2655	3539	1327	2655	3982	5309
10	208	417	625	833	312	625	937	1250
15	52	104	156	207	78	156	233	311
20	13	26	40	53	20	40	59	79
LMFA5□~LMFA6□ series attraction force (Cover type). Unit: N								
Air gap (mm)	LMFA52	LMFA53	LMFA54	LMFA62	LMFA63	LMFA64		
0	19674	29511	39348	29554	44331	59108		
0.45	16333	24500	32667	24536	36804	49072		
0.9	13700	20550	27400	20580	30870	41160		
1.35	11593	17389	23185	17414	26121	34828		
1.8	9870	14805	19740	14826	22239	29653		
2.25	8456	12684	16912	12703	19054	25405		
2.7	7272	10909	14545	10925	16387	21849		
3.15	6280	9419	12559	9433	14150	18866		
5	3534	5301	7069	5309	7964	10618		
10	832	1248	1664	1250	1874	2499		
15	207	311	414	311	467	622		
20	53	79	105	79	119	158		

■ Attraction force and air gap: Epoxy type




Figure 3.2.1.2.4 LMFA with epoxy type attraction force-air gap relationship graph

Table 3.2.1.2.5 LMFA0~2 with epoxy type attraction force-air gap comparison chart

LMFA0~LMFA2 series attraction force (Epoxy type). Unit: N											
Air gap (mm)	LMFA01	LMFA02	LMFA03	LMFA11	LMFA12	LMFA13	LMFA14	LMFA21	LMFA22	LMFA23	LMFA24
0	919	1839	2760	1684	3368	5052	6736	2533	5066	7599	10132
0.7	641	1282	1925	1174	2349	3523	4697	1766	3533	5299	7066
1.4	457	914	1372	837	1674	2511	3348	1259	2518	3777	5036
2.1	329	659	988	603	1206	1809	2412	907	1814	2721	3628
2.8	239	478	718	438	876	1314	1752	659	1318	1976	2635
3.5	175	350	525	320	640	960	1280	482	963	1445	1926
4.2	129	257	386	236	472	707	943	355	709	1064	1419
4.9	95	189	284	173	346	520	693	261	521	782	1042
10	11	22	33	20	40	60	79	30	60	90	119
15	1	3	4	3	5	8	11	4	8	12	16
20	0	0	0	0	0	0	0	0	0	0	0

Table 3.2.1.2.6 LMFA3~6 with epoxy type attraction force-air gap comparison chart

LMFA3□~LMFA4□ series attraction force (Epoxy type). Unit: N								
Air gap (mm)	LMFA31	LMFA32	LMFA33	LMFA34	LMFA41	LMFA42	LMFA43	LMFA44
0	6069	12138	18206	24275	9103	18206	27310	36413
0.7	4494	8989	13483	17978	6742	13483	20225	26966
1.4	3430	6860	10290	13720	5145	10290	15435	20580
2.1	2663	5326	7988	10651	3994	7988	11982	15977
2.8	2098	4195	6293	8391	3147	6293	9440	12586
3.5	1665	3330	4995	6660	2497	4995	7492	9989
4.2	1335	2670	4005	5340	2002	4005	6007	8010
4.9	1076	2152	3228	4304	1614	3228	4842	6456
10	245	490	734	979	367	734	1102	1469
15	61	122	184	245	92	184	275	367
20	15	31	46	62	23	46	69	93
30	0	0	0	0	0	0	0	0
LMFA5□~LMFA6□ series attraction force (Epoxy type). Unit: N								
Air gap (mm)	LMFA52	LMFA53	LMFA54	LMFA62	LMFA63	LMFA64		
0	24240	36360	48480	36413	54619	72826		
0.7	17951	26927	35903	26966	40450	53933		
1.4	13700	20550	27400	20580	30870	41160		
2.1	10635	15953	21271	15977	23965	31953		
2.8	8379	12568	16757	12586	18880	25173		
3.5	6650	9975	13300	9989	14984	19979		
4.2	5332	7998	10664	8010	12014	16019		
4.9	4297	6446	8595	6456	9683	12911		
10	978	1467	1956	1469	2203	2938		
15	244	367	489	367	551	734		
20	62	92	123	93	139	185		
30	0	0	0	0	0	0		

3.2.1.3 LMFP series

■ Continuous force/peak force and air gap: Cover type




Figure 3.2.1.3.1 LMFP with cover type Continuous force/peak force-air gap relationship graph

Table 3.2.1.3.1 LMFP with cover type Continuous force/peak force-air gap comparison chart

LMFP series Continuous force/peak force (Cover type). Unit: %		
Air gap (mm)	LMFP24	LMFP3~LMFP6
0.1	119	116
0.2	117	114
0.3	114	112
0.4	112	110
0.5	109	108
0.6	107	106
0.7	104	104
0.8	102	102
0.9	100	100
1	98	98
1.1	96	97
1.2	93	95
1.3	91	93
1.4	89	91
1.5	87	90
1.6	85	88
1.7	84	87
1.8	82	85

■ Continuous force/peak force and air gap: Epoxy type




Figure 3.2.1.3.2 LMFP with epoxy type Continuous force/peak force-air gap relationship graph

Table 3.2.1.3.2 LMFP with epoxy type Continuous force/peak force-air gap comparison chart

LMFP series Continuous force/peak force (Epoxy type). Unit: %		
Air gap (mm)	LMFP24	LMFP3~LMFP6
0.1	133	128
0.2	130	125
0.3	127	123
0.4	125	120
0.5	122	118
0.6	119	116
0.7	117	114
0.8	114	112
0.9	112	110
1	109	108
1.1	107	106
1.2	105	104
1.3	102	102
1.4	100	100
1.5	98	98
1.6	96	96
1.7	93	95
1.8	91	93

■ Attraction force and air gap: Cover type




Figure 3.2.1.3.3 LMFP with cover type attraction force-air gap relationship graph

Table 3.2.1.3.3 LMFP24~4□ with cover type attraction force-air gap comparison chart

LMFP24~LMFP4□ series attraction force (Cover type). Unit: N									
Air gap (mm)	LMFP24	LMFP31	LMFP32	LMFP33	LMFP34	LMFP41	LMFP42	LMFP43	LMFP44
0	7065	4404	8808	13213	17617	6606	13213	19819	26425
0.45	5674	3710	7419	11129	14839	5565	11129	16694	22258
0.9	4583	3121	6243	9364	12485	4682	9364	14046	18728
1.35	3710	2656	5313	7969	10625	3984	7969	11953	15938
1.8	3017	2273	4546	6819	9092	3409	6819	10228	13638
2.25	2466	1955	3910	5864	7819	2932	5864	8797	11729
2.7	2013	1687	3374	5061	6748	2531	5061	7592	10123
3.15	1653	1461	2922	4383	5845	2192	4383	6575	8767
5	737	828	1657	2485	3313	1243	2485	3728	4970
10	87	196	393	589	786	295	589	884	1179
15	11	50	99	149	198	74	149	223	297
20	0	12	24	37	49	18	37	55	73

Table 3.2.1.3.4 LMFP5□~6□ with cover type attraction force-air gap comparison chart

LMFP5□~LMFP6□ series attraction force (Cover type). Unit: N						
Air gap (mm)	LMFP52	LMFP53	LMFP54	LMFP62	LMFP63	LMFP64
0	17591	26387	35183	26425	39638	52851
0.45	14814	22226	29635	22258	33388	44517
0.9	12467	18701	24934	18728	28092	37456
1.35	10610	15914	21219	15938	23906	31875
1.8	9079	13618	18157	13638	20457	27276
2.25	7808	11712	15616	11729	17593	23458
2.7	6739	10108	13477	10123	15184	20245
3.15	5836	8754	11672	8767	13150	17534
5	3309	4963	6617	4970	7455	9940
10	785	1177	1569	1179	1768	2357
15	198	297	396	297	446	595
20	49	73	97	73	110	146

■ Attraction force and air gap: Epoxy type




Figure 3.2.1.3.4 LMFP with epoxy type attraction force-air gap relationship graph

Table 3.2.1.3.5 LMFP24~4□ with epoxy type attraction force-air gap comparison chart

LMFP24~LMFP4□ series attraction force (Epoxy type). Unit: N									
Air gap (mm)	LMFP24	LMFP31	LMFP32	LMFP33	LMFP34	LMFP41	LMFP42	LMFP43	LMFP44
0	9016	5355	10713	16068	21424	8034	16068	24102	32136
0.7	6380	4044	8089	12133	16177	6067	12133	18200	24266
1.4	4583	3121	6243	9364	12485	4682	9364	14046	18728
2.1	3319	2444	4888	7332	9776	3666	7332	10998	14664
2.8	2420	1936	3872	5807	7743	2904	5807	8711	11615
3.5	1773	1545	3091	4636	6181	2318	4636	6954	9272
4.2	1306	1241	2483	3725	4966	1862	3725	5587	7450
4.9	965	1004	2009	3013	4017	1506	3013	4519	6026
10	114	974	1949	2923	3898	1462	2923	4385	5847
15	18	230	460	689	919	345	689	1034	1379
20	0	57	114	171	228	85	171	256	342
30	-	15	30	45	60	22	45	67	90

Table 3.2.1.3.6 LMFP5□~6□ with epoxy type attraction force-air gap comparison chart

LMFP5□~LMFP6□ series attraction force (Epoxy type). Unit: N						
Air gap (mm)	LMFP52	LMFP53	LMFP54	LMFP62	LMFP63	LMFP64
0	21393	32090	42786	32136	448205	64273
0.7	16154	24231	32307	24266	36399	48532
1.4	12467	18701	24934	18728	28092	37456
2.1	9762	14643	19523	14664	21996	29328
2.8	7732	11598	15463	11615	17422	23229
3.5	6172	9258	12344	9272	13907	18543
4.2	4959	7439	9918	7450	11175	14899
4.9	4011	6017	8023	6026	9039	12052
10	3892	5838	7784	5847	8770	11693
15	918	1377	1836	1379	2068	2758
20	228	341	455	342	513	684
30	60	90	119	90	135	179

3.2.1.4 LMSC series

■ Attraction force and air gap





Figure 3.2.1.4.1 LMSC attraction force-air gap relationship graph

Table 3.2.1.4.1 LMSC attraction force-air gap comparison chart

Series	LMSC7(L) (WC)								
Air gap 1 (mm)	0	0.05	0.15	0.25	0.35	0.45	0.55	0.65	0.75
Air gap 2 (mm)	1.5	1.45	1.35	1.25	1.15	1.05	0.95	0.85	0.75
Attracting force (N)	2838	2633	2230	1840	1464	1090	724	361	0

3.2.1.5 LME seires

- LME-A series
- Continuous force/peak force and air gap: Cover type

Table 3.2.1.5.1 LME-A Continuous force/peak force-air gap relationship chart

Series	LME-A									
Air gap (mm)	0.1	0.2	0.3	0.4	0.5	0.6	0.7	0.8	0.9	1.0
Force (%)	113.0	110.4	108.1	106.1	103.1	100	97.7	95.1	92.5	89.8




Figure 3.2.1.5.1 LME-A with cover type Continuous force/peak force-air gap relationship graph

Series	LME-A										
Air gap (mm)	0	0.3	0.6	0.9	1.2	1.5	1.8	2.1	5.0	10.0	15.0
Force (%)	0	50	100	150	200	250	300	350	833	1666	2500

Table 3.2.1.5.2 LME-A Attraction force-air gap relationship chart




Figure 3.2.1.5.2 LME-A with cover type attraction force-air gap comparison graph

- LME-B series
- Continuous force/peak force and air gap: Cover type

Table 3.2.1.5.3 LME-B Continuous force/peak force-air gap relationship chart

Series	LME-B									
Air gap (mm)	0.1	0.2	0.3	0.4	0.5	0.6	0.7	0.8	0.9	1.0
Force (%)	113.5	110.5	107.6	104.8	102.3	100	97.6	95.3	93.0	90.6




Figure 3.2.1.5.3 LME-B with cover type Continuous force/peak force-air gap relationship graph

■ Attraction force and air gap: Cover type

Table 3.2.1.5.4 LME-B Attraction force-air gap relationship chart

Series	LME-B										
Air gap (mm)	0	0.3	0.6	0.9	1.2	1.5	1.8	2.1	5.0	10.0	15.0
Force (%)	0	50	100	150	200	250	300	350	833	1666	2500




Figure 3.2.1.5.4 LME-B with cover type attraction force-air gap relationship graph

3.2.2 Screw selection rules and instructions

- Before installing forcer and stator parts, please check the installation dimension first.
- Clean the forcer and stator parts installation surfaces and machine surfaces.
- For screws, please use screws comply with the DIN912 standard and strength of 10.9.
- Please use new screws and prevent repetitively remove and install forcer and stator as much as possible.
- Please select appropriate screws according to the screw hole/threaded hole dimensions of forcer and stator.
- During the installation of the stator, the screw head shall not exceed the stator surface.
- During the fastening of screws, please use torque wrench, and refer to the recommended fastening torque values indicated in the following table.
- In moving and vibrating structures, must be fastening of screws with screw glue.

3.2.2.1 Force and stator screw installation hole specification table

Table 3.2.2.1.1 LMFA forcer, stator screw installation hole specification table

LMFA series forcer		LMFA series stator	
LMFA0□(L)~LMFA2□(L)	M5x0.8Px10DP	LMF0S□(E)	Ø4.5THRU; Ø8x2DP
		LMF1S□(E)	Ø5.5THRU; Ø10x1.5DP
LMFP24	M5x0.8Px9DP	LMF2S□(E)	Ø5.5THRU; Ø10x3.5DP
		LMF3S□(E)	Ø9THRU; Ø15x6DP
LMFA3□(L)~LMFA6□(L)	M8x1.25Px14DP	LMF4S□(E)	Ø9THRU; Ø15x6DP
		LMF5S□E	Ø9THRU; Ø15x6DP
LMFP3□~6□	M8x1.25Px12.5DP	LMF6S□E	Ø6.5THRU; Ø10.5x6DP

Table 3.2.2.1.2 LMSA forcer, stator screw installation hole specification table

LMSA series forcer			LMSA series stator	
	Installation hole		Cover type	Epoxy type
LMSA0□ LMSA0□-Z	M5x0.8Px4DP	LMSA0S□(EA)	Ø4.5 THRU	Ø4.5 THRU, Ø8x5.6DP
LMSA1□(L) ~LMSA3□(L) LMSA1□-Z ~LMSA3□-Z	M4x0.7Px4DP	LMSA1S□(EA)	Ø4.5 THRU	Ø4.5 THRU, Ø8x5.6DP
		LMSA2S□(EA)	Ø5.5 THRU	Ø5.5 THRU, Ø10x5.6DP
		LMSA3S□(EA)	Ø5.5 THRU	Ø5.5 THRU, Ø10x5.6DP
		LMSACS□(EA)	Ø5.5 THRU	Ø5.5 THRU, Ø10x5.6DP
LMSAC□(L)				

Table 3.2.2.1.3 LMSS forcer, stator screw installation hole specification table

LMSS series forcer		LMSS series stator	
LMSS11	M3x0.5Px5DP	LMSS1S□	Ø4.5 THRU

Table 3.2.2.1.4 LMSC forcer, stator screw installation hole specification table

LMSC series forcer		LMSC series stator	
LMSC7(L)	M8x1.25Px12DP	LMS3S□	Ø6.5 THRU, Ø11x4DP

Table 3.2.2.1.5 LMC forcer, stator screw installation hole specification table

LMC series forcer			LMC series stator	
	Bottom installation hole	Side installation hole		
LMCA	M3x0.5Px4.5DP	M4x0.7Px5DP	LMCAS□	Ø5.5 THRU, Ø9.5x8DP
LMCB			LMCBS□	Ø5.5 THRU, Ø9.5x8DP
LMCC			LMCCS□	Ø6.5 THRU, Ø11x10DP
LMCD	M5x0.8Px6DP	M4x0.7Px8DP	LMCDS□	Ø6.5 THRU, Ø11x8DP
LMCE			LMCES□	Ø6.5 THRU, Ø11x8DP
LMCF		M5x0.8Px9DP	LMCFS□	Ø6.5 THRU, Ø11x8DP

Table 3.2.2.1.6 LMC-EF forcer, stator screw installation hole specification table

LMC-EF series forcer		LMC-EF series stator	
	Bottom installation hole		
LMC-EFC	M4x0.7Px5DP M4x0.7Px12DP	LMC-EFCS□	Ø4.2 THRU, Ø7.5x6.35DP
LMC-EFE	M4x0.7Px5DP M4x0.7Px12DP	LMC-EFES□	Ø5.5 THRU, Ø9.5x6.85DP
LMC-EFF	M5x0.8Px10DP M5x0.8Px12DP	LMC-EFFS□	Ø5.5 THRU, Ø9.5x8DP

Table 3.2.2.1.7 LMC-HUB forcer, stator screw installation hole specification table

LMC-HUB series forcer			LMC-HUB series stator	
	Bottom installation hole	Side installation hole		
LMC-HUB	M3x0.5P THRU	M3x0.5Px3DP	LMC-HUBS□	Ø4.5 THRU, Ø8x4.5DP

Table 3.2.2.1.8 LMT forcer screw installation hole specification table


LMT series forcer	
LMT2	M3x0.5Px5DP
LMT6	M3x0.5Px5DP
LMTA	M4x0.7Px6DP
LMTB	M6x1.0Px9DP
LMTC	M8x1.25Px12DP

Table 3.2.2.1.6 LME forcer, stator screw installation hole specification table

LME series forcer		LME series stator	
	Installation hole		Cover type
LME-A-12 LME-A-22(L)	M3x0.5Px5DP	LME-A-1S□ LME-A-2S□	Ø4.5 THRU
LME-B-13 LME-B-22 LME-B-23(L)	M4x0.7Px4DP	LME-B-1S□ LME-B-2S□	Ø4.5 THRU


3.2.2.2 Forcer recommended screw fastening depth table

Table 3.2.2.2.1 Forcer screw fastening depth table

Forcer specification	Screw specification	Screw fastening depth H(mm)	Schematic illustration
LMSS	M3	4.5 0/-1	
LMSA0□/LMSA0□-Z	M5	3.5 0/-1	
LMSA1□~C□/LMSA1□-Z~3□-Z	M4	3.5 0/-1	
LME-A	M3	5 0/-1	
LME-B	M4	5 0/-1	
LMFA0□~2□	M5	9 0/-2.5	
LMFP24	M5	8 0/-2	
LMFA3□~6□	M8	12 0/-3.5	
LMFP3□~6□	M8	11 0/-3	
LMSC7	M8	11 0/-3	
LMCA~C	M3(bottom)	4 0/-1	
	M4(side)		
LMCD~E	M5(bottom)	5 0/-1	
	M4(side)	6 0/-2	
LMCF	M5(bottom)	5 0/-1	
	M5(side)	8 0/-2	
LMC-EFC/EFE	M4	4 0/-1	
		8 0/-3	
LMC-EFF	M5	8 0/-2s	
LMT2□	M3	4.5 0/-1	
LMT6□			
LMTA□	M4	5 0/-1	
LMTB□	M6	8 0/-2	
LMT□	M8	11 0/-3	

Note:LMC-EFC series forcer bottom threaded holes have two types of depths, please refer to the catalog drawings.

Table 3.2.2.2.2 Screw fastening depth table for forcer equipped with precision water-cooling

Forcer specification	Screw specification	Screw fastening depth H(mm)	Schematic illustration
LMFA3□~6□	M8	24 ⁰ / _{-3.5}	
LMFP3□~6□	M8	23 ⁰ / ₋₃	

3.2.2.3 Stator recommended screw fastening minimum depth table

Table 3.2.2.3.1 Stator screw fastening depth table

Material	Carbon steel	Cast iron	Aluminum alloy
Fastening depth	1.2 x d	1.6 x d	1.8 x d

Note: The maximum fastening depth is determined based on the threaded hole on the customer's machine.

3.2.2.4 Forcer and stator recommended screw torque table

Table 3.2.2.4.1 Screw torque specification table

Screw dimension	Torque (kgf-cm)	Torque (N-m)
M3x0.5P	15	1.5
M4x0.7P	34	3.3
M5x0.8P	69	6.8
M6x1.0P	118	11.6
M8x1.25P	286	28.1

3.3 Electrical connection

3.3.1 Cable

3.3.1.1 Standard specification of power cable

The lengths of power cable and temperature cable for standard linear motor are from 0.5m to 1.2m. The unit of length for cable is 100mm. Cable outlets could be with connectors or with open ends as shown in figure 3.3.1.1.1.




Figure 3.3.1.1.1 Outlet specifications for power cable

3.3.1.2 Recommended construction method for grounding protection

- Shielding must be equipped with power cable or temperature cable. Also, the shielding must be grounded (as figure 3.3.1.2.1 shows).
- After stripping off the shielding, the whole shielding can be cut to an appropriate length for more convenient operations. Do not cut part of the shielding; otherwise, the shielding might break easily and effect the grounding efficiency.




Figure 3.3.1.2.1 Recommended grounding method

3.3.1.3 Recommended construction method for ironless linear motor grounding protection

For the ironless linear motor power cable, it is recommended to use an isolation net for the grounding protection. The isolation net is divided into two parts, one part for the grounding, and the other part is wrapped with copper foil to connect to the metal casing, as shown in figure 3.3.1.3.1.





Figure 3.3.1.3.1 ironless linear motor grounding protection

3.3.1.4 Recommended installation method of extension cable for LMSA-Z series

■ Extension cable manufacture



- (1) Please refer to the Table 3.3.1.4.1 for the specification of the length of the cord end terminal.
- (2) Please refer to the Table 3.3.1.4.1 for the specification of the cross-sectional area of the copper wire of the cable.
- (3) Please refer to the Figure3.3.1.4.1 for the connector pin.

Table3.3.1.4.1 Specifications

Length of the cord end terminal (L) (mm)	Cross-sectional area of the copper wire	
	AWG	DIN (mm ²)
10	22	0.5
10	20	0.75
10	18	1.0





Figure3.3.1.4.1 Connector pin

■ Connector installation


The motor has been connected to the connector.

When plugging and unplugging the connector, pay attention that it must be inserted to the bottom and all four buckles must be fully buckled in.

The buckle position is shown in Figure3.3.1.4.2 The correct installation is shown in Figure3.3.1.4.3 .



Incorrect installation will lead to operational risks, as shown in Figures3.3.1.4.4~3.3. 1.4.6:



■ Motor and extension cable installation

The motor has been connected to the connector, and the connector can be removed to make an extension cable. Refer to Figure3.3.1.4.7.




Figure3.3.1.4.7 Connect the motor to the extension cable

If the motor is used in a high dust environment, it is recommended to install a dust cover on the machine.
For detailed installation methods of heat-shrinkable tube as follow :

■ Installation Notes

- (1) Take out the motor from package(Fig. 3.3.1.4.8) (Don't pull out the green connector, and confirm that the connector must be inserted to the end and the four buckles must be fully buckled in), and prepare your own heat-shrinkable tube. (Fig. 3.3.1.4.9)
- (2) Heat-shrinkable tube $\Phi=22\text{mm}$. The length of small heat-shrinkable tube: 9mm, the length of big heat-shrinkable tube:70mm.
- (3) Put ① Small heat-shrinkable tube on the buckles of the motor connector (marked in red below), and then use heat gun to tighten it. (Fig. 3.3.1.4.10)
- (4) Put ② Big heat-shrinkable tube in the ③ extension cable.
- (5) Connect extension cable of step3. to ④ the connector on the motor. (Fig. 3.3.1.4.12)
*Please refer to Table 3.3.1.4.1 for specifications of the Cord end terminal on the side of the extension cable that is connected to the motor connector.
*For motor connector pins, please refer to Figure 3.3.1.4.1.
- (6) Check the ① has cooled. Place ② on ④ the connector on the motor. (Fig. 3.3.1.4.13)
- (7) Use ⑤ heat gun to tighten ②. the big heat-shrinkable tube. The tighten direction is as shown in the Figure (Fig. 3.3.1.4.14)
- (8) Complete the heat-shrinkable tube coating. (Fig. 3.3.1.4.15)
- (9) Finally, install the motor including the extension cable in step (7) on the machine.



Figure 3.3.1.4.8 Package of Motor




Figure 3.3.1.4.9 Motor, heat-shrinkable tube




Figure 3.3.1.4.10 Location of small heat-shrinkable



Figure 3.3.1.4.11 Big heat-shrinkable tube in the extension cable




Figure3.3.1.4.12 The extension cable connect with the motor connector




Figure3.3.1.4.13 Big heat-shrink tube moved to motor connector




Figure3.3.1.4.14 Heat gun to tighten




Figure3.3.1.4.15 Finish

The motor cable should be fixed by cable tie and cable tray after assembling the forcer on the forcer plate. Also, the extension cable should be fixed by the cable tie and put into the cable chain to ensure it works in normal, as shown in Figure 3.3.1.4.16 and Figure 3.3.1.4.17.

If the cable doesn't be installed properly as shown in figure3.3.1.4.18 and figure3.3.1.4.19, failures such as shaking and worn-out might be happened and caused abnormal situation.

■ Recommended installation method



Figure 3.3.1.4.16 Fix the motor cable by cable tie and cable tray






Figure 3.3.1.4.17 Fix the extension cable by cable tie and put into the cable

■ Improper installation method





Figure 3.3.1.4.18 Extension cable is not fixed




Figure 3.3.1.4.19 Extension cable is not put into the cable chain

3.3.1.5 Motor with connector series

For motor with standard connector, the recommended installation methods of standard extension cable are given as follows.

- The copper pillar accessories are attached to the motor extension cable for standard shipment.
- Choose without copper pillar design: Customers get their own adaption board mounting bracket with 4 internal threads to make the screws be fixed. Usage examples are described in figure 3.3.1.5.2(left).
- Choose with copper pillar design: Customers adopt through-hole on their own adaption board mounting bracket to make the screws go through. (the part shown in the red circle of figure 3.3.1.5.1) to fix the connectors. Usage examples are described in figure 3.3.1.5.2(right).





Figure 3.3.1.5.1 Connecting diagram

Standard : Without copper pillar design


external thread



Example : Connect with fixed board

Fixed board
(with internal thread)


Extension cable



Motor

With accessories : With copper pillar design


With copper pillar



Example : Connect with copper pillar

Fixed board
(with through hole) copper pillar

Extension cable






































Motor




















Figure 3.3.1.5.2 Connecting diagram




3.3.1.6 Connector selection and pin assignment


Table 3.3.1.6.1 Connection selection wiring chart

Model	Connector	Pin ⁽¹⁾																		
LMSA series	  D-Sub 9-Pin Connector	<table><tr><th colspan="2">Wiring Diagram</th></tr><tr><th>D-Sub (Male)</th><th>Signal</th></tr><tr><td>A1</td><td>V</td></tr><tr><td>A2</td><td>U</td></tr><tr><td>A3</td><td>W</td></tr><tr><td>A4</td><td>GND</td></tr><tr><td>1</td><td>T+</td></tr><tr><td>3</td><td>T-</td></tr><tr><td>CASE</td><td></td></tr></table>	Wiring Diagram		D-Sub (Male)	Signal	A1	V	A2	U	A3	W	A4	GND	1	T+	3	T-	CASE	
	Wiring Diagram																			
D-Sub (Male)	Signal																			
A1	V																			
A2	U																			
A3	W																			
A4	GND																			
1	T+																			
3	T-																			
CASE																				
LMSA-Z series	   Pluggable Terminal Blocks	<table><tr><th colspan="2">Wiring Diagram</th></tr><tr><th>Pluggable Terminal Blocks</th><th>Cable Signal</th></tr><tr><td>U</td><td>U</td></tr><tr><td>V</td><td>V</td></tr><tr><td>W</td><td>W</td></tr><tr><td>T+</td><td>T+</td></tr><tr><td>T-</td><td>T-</td></tr><tr><td>G</td><td>G</td></tr></table>	Wiring Diagram		Pluggable Terminal Blocks	Cable Signal	U	U	V	V	W	W	T+	T+	T-	T-	G	G		
	Wiring Diagram																			
Pluggable Terminal Blocks	Cable Signal																			
U	U																			
V	V																			
W	W																			
T+	T+																			
T-	T-																			
G	G																			

LMFA series (M23)	<div><p>Metal connector (Angled Rotatable) (Male)</p></div>	<table><tr><th colspan="2">Wiring Diagram</th></tr><tr><th>Metal connector (Male)</th><th>Signal</th></tr><tr><td>1</td><td>U</td></tr><tr><td>4</td><td>V</td></tr><tr><td>3</td><td>W</td></tr><tr><td>(2) </td><td rowspan="2"></td></tr><tr><td>Case</td></tr><tr><td>A</td><td>T1+(Gray)</td></tr><tr><td>B</td><td>T1-(Gray)</td></tr><tr><td>C</td><td>T2+(Red)</td></tr><tr><td>D</td><td>T2-(White)</td></tr></table> <div><div> PTC SNM120</div><div> Pt1000</div></div>	Wiring Diagram		Metal connector (Male)	Signal	1	U	4	V	3	W	(2) 		Case	A	T1+(Gray)	B	T1-(Gray)	C	T2+(Red)	D	T2-(White)
	Wiring Diagram																						
	Metal connector (Male)	Signal																					
1	U																						
4	V																						
3	W																						
(2) 																							
Case																							
A	T1+(Gray)																						
B	T1-(Gray)																						
C	T2+(Red)																						
D	T2-(White)																						
	<div><p>Metal connector (Male)</p></div>	<table><tr><th colspan="2">Wiring Diagram</th></tr><tr><th>Metal connector (Male)</th><th>Signal</th></tr><tr><td>1</td><td>U</td></tr><tr><td>4</td><td>V</td></tr><tr><td>3</td><td>W</td></tr><tr><td>(2) </td><td rowspan="2"></td></tr><tr><td>Case</td></tr><tr><td>A</td><td>T1+(Gray)</td></tr><tr><td>B</td><td>T1-(Gray)</td></tr><tr><td>C</td><td>T2+(Red)</td></tr><tr><td>D</td><td>T2-(White)</td></tr></table> <div><div> PTC SNM120</div><div> Pt1000</div></div>	Wiring Diagram		Metal connector (Male)	Signal	1	U	4	V	3	W	(2) 		Case	A	T1+(Gray)	B	T1-(Gray)	C	T2+(Red)	D	T2-(White)
Wiring Diagram																							
Metal connector (Male)	Signal																						
1	U																						
4	V																						
3	W																						
(2) 																							
Case																							
A	T1+(Gray)																						
B	T1-(Gray)																						
C	T2+(Red)																						
D	T2-(White)																						
	<div><p>Metal connector (Male)</p></div>	<table><tr><th colspan="2">Wiring Diagram</th></tr><tr><th>Metal connector (Male)</th><th>Signal</th></tr><tr><td>1</td><td>U</td></tr><tr><td>4</td><td>V</td></tr><tr><td>3</td><td>W</td></tr><tr><td>2()</td><td rowspan="2"></td></tr><tr><td>Case</td></tr><tr><td>A</td><td>T1+</td></tr><tr><td>B</td><td>T1-</td></tr><tr><td>C</td><td>T2+</td></tr><tr><td>D</td><td>T2-</td></tr></table> <div><div> PTC SNM120</div><div> Pt1000</div></div>	Wiring Diagram		Metal connector (Male)	Signal	1	U	4	V	3	W	2()		Case	A	T1+	B	T1-	C	T2+	D	T2-
Wiring Diagram																							
Metal connector (Male)	Signal																						
1	U																						
4	V																						
3	W																						
2()																							
Case																							
A	T1+																						
B	T1-																						
C	T2+																						
D	T2-																						

LMFP series	<div><p>Metal connector (M23)</p></div>	<table><tr><th colspan="2">Wiring Diagram</th></tr><tr><th>Metal connector (Male)</th><th>Signal</th></tr><tr><td>1</td><td>U</td></tr><tr><td>4</td><td>V</td></tr><tr><td>3</td><td>W</td></tr><tr><td>2()</td><td rowspan="2"></td></tr><tr><td>Case</td></tr><tr><td>A</td><td>T1+</td></tr><tr><td>B</td><td>T1-</td></tr><tr><td>C</td><td>T2+</td></tr><tr><td>D</td><td>T2-</td></tr></table> <div><div> PTC SNM120</div><div> Pt1000</div></div>	Wiring Diagram		Metal connector (Male)	Signal	1	U	4	V	3	W	2()		Case	A	T1+	B	T1-	C	T2+	D	T2-
	Wiring Diagram																						
Metal connector (Male)	Signal																						
1	U																						
4	V																						
3	W																						
2()																							
Case																							
A	T1+																						
B	T1-																						
C	T2+																						
D	T2-																						
	<div><p>Metal connector (M40)</p></div>	<table><tr><th colspan="2">Wiring Diagram</th></tr><tr><th>Metal connector (Male)</th><th>Signal</th></tr><tr><td>U</td><td>U</td></tr><tr><td>V</td><td>V</td></tr><tr><td>W</td><td>W</td></tr><tr><td></td><td rowspan="2"></td></tr><tr><td>Case</td></tr><tr><td>1</td><td>T1+</td></tr><tr><td>2</td><td>T1-</td></tr><tr><td>+</td><td>T2+</td></tr><tr><td>-</td><td>T2-</td></tr></table> <div><div> PTC SNM120</div><div> Pt1000</div></div>	Wiring Diagram		Metal connector (Male)	Signal	U	U	V	V	W	W			Case	1	T1+	2	T1-	+	T2+	-	T2-
Wiring Diagram																							
Metal connector (Male)	Signal																						
U	U																						
V	V																						
W	W																						
																							
Case																							
1	T1+																						
2	T1-																						
+	T2+																						
-	T2-																						
LMSC7	<div><p>D-Sub 9-Pin Connector</p></div>	<table><tr><th colspan="2">Wiring Diagram</th></tr><tr><th>D-Sub (Male)</th><th>Signal</th></tr><tr><td>A1</td><td>V</td></tr><tr><td>A2</td><td>U</td></tr><tr><td>A3</td><td>W</td></tr><tr><td>A4</td><td>GND</td></tr><tr><td>1</td><td>T+</td></tr><tr><td>3</td><td>T-</td></tr><tr><td>CASE</td><td></td></tr></table>	Wiring Diagram		D-Sub (Male)	Signal	A1	V	A2	U	A3	W	A4	GND	1	T+	3	T-	CASE				
Wiring Diagram																							
D-Sub (Male)	Signal																						
A1	V																						
A2	U																						
A3	W																						
A4	GND																						
1	T+																						
3	T-																						
CASE																							

LMSS11	<div><p>M16-P5P (Male)</p></div>	<table><tr><th colspan="2">Wiring Diagram</th></tr><tr><th>M16-P5P (Male)</th><th>Signal</th></tr><tr><td>1</td><td>V</td></tr><tr><td>2</td><td>U</td></tr><tr><td>3</td><td>W</td></tr><tr><td>Case</td><td>GND</td></tr><tr><td>4</td><td>T+</td></tr><tr><td>5</td><td>T-</td></tr></table>	Wiring Diagram		M16-P5P (Male)	Signal	1	V	2	U	3	W	Case	GND	4	T+	5	T-		
Wiring Diagram																				
M16-P5P (Male)	Signal																			
1	V																			
2	U																			
3	W																			
Case	GND																			
4	T+																			
5	T-																			
LMC A/B/C/D/E/ EFC/HUB	<div><p>M16-P5P (Male)</p></div>	<table><tr><th colspan="2">Wiring Diagram</th></tr><tr><th>M16-P5P (Male)</th><th>Signal</th></tr><tr><td>1</td><td>V</td></tr><tr><td>2</td><td>U</td></tr><tr><td>3</td><td>W</td></tr><tr><td>Case</td><td>GND</td></tr><tr><td>4</td><td>T+</td></tr><tr><td>5</td><td>T-</td></tr></table>	Wiring Diagram		M16-P5P (Male)	Signal	1	V	2	U	3	W	Case	GND	4	T+	5	T-		
Wiring Diagram																				
M16-P5P (Male)	Signal																			
1	V																			
2	U																			
3	W																			
Case	GND																			
4	T+																			
5	T-																			
LMC F/EFE/EFF	<div><p>D-Sub 9-Pin Connector</p></div>	<table><tr><th colspan="2">Wiring Diagram</th></tr><tr><th>D-Sub (Male)</th><th>Signal</th></tr><tr><td>A1</td><td>V</td></tr><tr><td>A2</td><td>U</td></tr><tr><td>A3</td><td>W</td></tr><tr><td>A4</td><td>GND</td></tr><tr><td>1</td><td>T+</td></tr><tr><td>3</td><td>T-</td></tr><tr><td>CASE</td><td></td></tr></table>	Wiring Diagram		D-Sub (Male)	Signal	A1	V	A2	U	A3	W	A4	GND	1	T+	3	T-	CASE	
Wiring Diagram																				
D-Sub (Male)	Signal																			
A1	V																			
A2	U																			
A3	W																			
A4	GND																			
1	T+																			
3	T-																			
CASE																				

LMT 2/6/A/B/C		
	M16-P5P (Male)	

Note:

The GND or ground symbol (\perp) of product are both qualified for shipment. Our Approval drawings will show one of the markings.

3.3.2 Forcer parallel design

Linear motors can be co-axially grouped with multiple sets of forcers in parallel for use. While multiple sets of forcers are installed in parallel, it is necessary to confirm that the motor models are identical to each other. In addition, assembly shall be performed according to the outlet direction and the parallel span (ΔX) design in order to ensure that the linear motor phases are the same before activation. The parallel span and installation outlet relationship of each series motor will be explained in a later chapter in more detail. For the motor parallel parameter calculation, please refer to table 3.3.2.1.

Table 3.3.2.1 Motor parallel parameter calculation

	Single unit	2 units in parallel	3 units in parallel	4 units in parallel
Resistance (Ω)	A	A/2	A/3	A/4
Inductance (mH)	B	B/2	B/3	B/4
Force constant (N/Arms)	C	C	C	C
Back EMF constant (Vrms/(m/s))	D	D	D	D
Continuous current (Arms)	E	E*2	E*3	E*4
Peak current (Arms)	F	F*2	F*3	F*4
Continuous force (N)	G	G*2	G*3	G*4
Peak force (N)	H	H*2	H*3	H*4

3.3.2.1 Linear motor moving direction

Definition of the positive direction of linear motor as follow: Input U/V/W in sequence, the initial moving direction is the positive direction.

The positive direction of linear motor movement is as follows:

■ Iron core:




Figure 3.3.2.1.1 Connecting diagram

■ Ironless:




Figure 3.3.2.1.2 Connecting diagram

3.3.2.2 LMSA/LMSA-Z/LME linear motor series




Figure 3.3.2.2.1 LMSA/LME/LMSA-Z/LME linear motor parallel connection illustration

Table 3.3.2.2.1 LMSA/LMSA-Z/LME parallel wiring chart

Motor type		Same side			Outward			Inward		
Motor 1		U	V	W	U	V	W	U	V	W
Motor 2		U	V	W	W	V	U	W	V	U
LMSA/LMSA-Z	ΔX (2P=30mm)	$n*2P$ (n is an integer)			$65+n*2P$ (n=0,1,2...etc.)			$65+n*2P$ (n=0,1,2...etc.)		
LME-A	ΔX (2P=24mm)	$n*2P$ (n is an integer)			$50+n*2P$ (n=0,1,2...etc.)			$102+n*2P$ (n=0,1,2...etc.)		
LME-B	ΔX (2P=30mm)	$n*2P$ (n is an integer)			$47.5+n*2P$ (n=0,1,2...etc.)			$112.5+n*2P$ (n=0,1,2...etc.)		

3.3.2.3 LMFA water-cooling linear motor series




Figure 3.3.2.3.1 LMFA/LMFP linear motor parallel connection illustration

Table 3.3.2.3.1 LMFA/LMFP parallel wiring chart

LMFA/LMFP	Same side			Outward			Inward			Model
Motor 1	U	V	W	U	V	W	U	V	W	
Motor 2	U	V	W	W	V	U	W	V	U	
ΔX (2P=30mm)	$n \cdot 2P$ (n is an integer)			$82.5 + n \cdot 2P$ (n=0,1,2...etc.)			$322.5 + n \cdot 2P$ (n=0,1,2...etc.)			LMFA0~2 series LMFP24 series
ΔX (2P=46mm)	$n \cdot 2P$ (n is an integer)			$127 + n \cdot 2P$ (n=0,1,2...etc.)			$402 + n \cdot 2P$ (n=0,1,2...etc.)			LMFA3~6 series LMFP3~6 series

3.3.2.4 LMSC magnetic brake linear motor series




Figure 3.3.2.4.1 LMSC linear motor parallel connection illustration

Table 3.3.2.4.1 LMSC parallel wiring chart

LMSC	Same side			Outward			Inward		
Motor 1	U	V	W	U	V	W	U	V	W
Motor 2	U	V	W	W	V	U	W	V	U
ΔX (2P=32mm)	320+n*2P (n=1,2...etc.)								

3.3.2.5 LMSS linear motor series




Figure 3.3.2.5.1 LMSS linear motor parallel connection illustration

Table 3.3.2.5.1 LMSS parallel wiring chart

LMSS	Same side			Outward			Inward		
Motor 1	U	V	W	U	V	W	U	V	W
Motor 2	U	V	W	V	U	W	V	U	W
ΔX (2P=20mm)	$120+n*2P$ (n=0,1,2...etc.)			$48+n*2P$ (n=0,1,2...etc.)			$48+n*2P$ (n=0,1,2...etc.)		

3.3.2.6 LMC ironless linear motor series

■ LMC A/B/C/D/E/F series




Figure 3.3.2.6.1 LMC A/B/C/D/E/F linear motor parallel connection illustration

Table 3.3.2.6.1 LMCA/B/C parallel wiring chart

LMCA/B/C	Same side			Outward			Inward		
Linear motor A	U	V	W	U	V	W	U	V	W
Linear motor B	U	V	W	W	V	U	W	V	U
ΔX (2P=32mm)	32+n*2P (n=1,2...etc.)			18+n*2P (n=1,2...etc.)			46+n*2P (n=1,2...etc.)		

Table 3.3.2.6.2 LMCD/E/F parallel wiring chart

LMCD/E/F	Same side			Outward			Inward		
Linear motor A	U	V	W	U	V	W	U	V	W
Linear motor B	U	V	W	U	W	V	V	U	W
ΔX (2P=60mm)	60+n*2P (n=1,2...etc.)			50+n*2P (n=0,1,2...etc.)			50+n*2P (n=0,1,2...etc.)		

■ LMC-EF series




Figure 3.3.2.6.2 LMC-EF linear motor parallel connection illustration

Table 3.3.2.6.3 LMC-EF parallel wiring chart

LMC-EFC	Same side			Outward			Inward		
Linear motor A	U	V	W	U	V	W	U	V	W
Linear motor B	U	V	W	U	W	V	V	U	W
ΔY (2P=60mm)	n*2P			90+n*2P			10+n*2P		
ΔZ	n*2P			100+n*2P			n*2P		
n	LMC-EFC1 : n=2,3,4... LMC-EFC2 : n=3,4,5... LMC-EFC3 : n=4,5,6... LMC-EFC4 : n=5,6,7...			LMC-EFC1 : n=0,1,2... LMC-EFC2 : n=2,3,4... LMC-EFC3 : n=4,5,6... LMC-EFC4 : n=6,7,8...			n=2,3,4...		
LMC-EFE	Same side			Outward			Inward		
Linear motor A	U	V	W	U	V	W	U	V	W
Linear motor B	U	V	W	U	W	V	V	U	W
ΔY (2P=60mm)	n*2P			90+n*2P			10+n*2P		
ΔZ	n*2P			99+n*2P			1+n*2P		
n	LMC-EFE1 : n=2,3,4... LMC-EFE2 : n=3,4,5... LMC-EFE3 : n=4,5,6... LMC-EFE4 : n=5,6,7... LMC-EFE5 : n=6,7,8... LMC-EFE6 : n=7,8,9...			LMC-EFE1 : n=0,1,2... LMC-EFE2 : n=2,3,4... LMC-EFE3 : n=4,5,6... LMC-EFE4 : n=6,7,8... LMC-EFE5 : n=8,9,10... LMC-EFE6 : n=10,11,12...			n=2,3,4...		
LMC-EFF	Same side			Outward			Inward		
Linear motor A	U	V	W	U	V	W	U	V	W
Linear motor B	U	V	W	U	W	V	V	U	W
ΔZ (2P=60mm)	n*2P			89+n*2P			11+n*2P		
n	LMC-EFFx: n=x+1, x+2, x+3...			LMC-EFFx: n=(x-1)*2,(x-1)*2+1,(x-1)*2+2...			n=2,3,4...		
x(1~9)	x=1~9			x=1~9					
x(A~D)	x=10~13			x=10~13					

■ LMC-HUB series




Figure 3.3.2.6.3 LMC-HUB linear motor parallel connection illustration

Table 3.3.2.6.4 LMC-HUB parallel wiring chart

Motor type		Same side			Outward			Inward		
Linear motor A		U	V	W	U	V	W	U	V	W
Linear motor B		U	V	W	V	U	W	V	U	W
LMC-HUB1	ΔX (2P=24mm)	72+n*2P (n=1, 2...etc.)			11+n*2P (n=1, 2...etc.)			35+n*2P (n=1, 2...etc.)		
LMC-HUB2	ΔX (2P=24mm)	120+n*2P (n=1, 2...etc.)								

3.3.2.7 LMT Tubular linear motor series




Figure 3.3.2.7.1 LMT linear motor parallel connection illustration

Table 3.3.2.7.1 LMT same cable outlet direction parallel wiring chart

LMT 2D/2Q	Same side			LMT 2T	Same side		
Linear motor A	U	V	W	Linear motor A	U	V	W
Linear motor B	U	V	W	Linear motor B	U	V	W
ΔX (2P=48mm)	n*2P-8.2 (n=1,2,3...)			ΔX (P=24mm)	(2n-1)*P-8.2 (n=1,2,3...)		
LMT 6D/6Q	Same side			LMT 6T	Same side		
Linear motor A	U	V	W	Linear motor A	U	V	W
Linear motor B	U	V	W	Linear motor B	U	V	W
ΔX (2P=60mm)	n*2P-10.5 (n=1,2,3...)			ΔX (P=30mm)	(2n-1)*P-10.5 (n=1,2,3...)		
LMT A2/A4	Same side			LMT A3	Same side		
Linear motor A	U	V	W	Linear motor A	U	V	W
Linear motor B	U	V	W	Linear motor B	U	V	W
ΔX (2P=72mm)	n*2P-12 (n=1,2,3...)			ΔX (P=36mm)	(2n-1)*P-12 (n=1,2,3...)		
LMT B2/B4	Same side			LMT B3	Same side		
Linear motor A	U	V	W	Linear motor A	U	V	W
Linear motor B	U	V	W	Linear motor B	U	V	W
ΔX (2P=90mm)	n*2P-15 (n=1,2,3...)			ΔX (P=45mm)	(2n-1)*P-15 (n=1,2,3...)		
LMT C2/C4/C6	Same side			LMT C3/C5	Same side		
Linear motor A	U	V	W	Linear motor A	U	V	W
Linear motor B	U	V	W	Linear motor B	U	V	W
ΔX (2P=120mm)	n*2P-20 (n=1,2,3...)			ΔX (P=60mm)	(2n-1)*P-20 (n=1,2,3...)		

Talbe3.3.2.7.2 LMT different cable outlet directions parallel wiring chart

LMT 2 series	Outward			Inward		
Linear motor A	U	V	W	V	U	W
Linear motor B	V	U	W	U	V	W
ΔX (2P=48mm)	n*2P-8.2 (n=1,2,3...)					
LMT 6 series	Outward			Inward		
Linear motor A	U	V	W	V	U	W
Linear motor B	V	U	W	U	V	W
ΔX (2P=60mm)	n*2P-10.5 (n=1,2,3...)					
LMT A series	Outward			Inward		
Linear motor A	U	V	W	V	U	W
Linear motor B	V	U	W	U	V	W
ΔX (2P=72mm)	n*2P-12 (n=1,2,3...)					
LMT B series	Outward			Inward		
Linear motor A	U	V	W	V	U	W
Linear motor B	V	U	W	U	V	W
ΔX (2P=90mm)	n*2P-15 (n=1,2,3...)					
LMT C series	Outward			Inward		
Linear motor A	U	V	W	V	U	W
Linear motor B	V	U	W	U	V	W
ΔX (2P=120mm)	n*2P-20 (n=1,2,3...)					

3.3.3 Hall accessories

3.3.3.1 Hall sensor

WARNING





Risk of injury from uncontrolled motor movements!



- ◆ An incorrectly installed or connected Hall sensor may cause uncontrolled motor movements which can lead to injuries or might damage the machine.
- ◆ Hall sensor may only be connected by specialist personnel.


For the driving control of a linear motor, Hall sensors can be selected and purchased to find the optimal electrical angle. Hall sensors can be divided into digital and analog sensors according to the signal output method. A digital hall sensor has relatively better anti-interference capability; however, it has a maximum electrical angle error of 30° . An Analog Hall sensor is prone to be affected by interference; nonetheless, it has no electrical angle error. The following provides further description on the hall sensors for iron core and ironless linear motors respectively.


Table 3.3.3.1.1 Hall sensor specification comparison chart with digital signal for iron core linear motors

Hall sensor specification	Output signal	Outlet mode	Hall sensor Illustration of dimensions	Applicable linear motor series
LMAHS	Digital	Connector		LMS Series
LMAHS-W	Digital	Bare cable		
LMAHSA	Digital	Connector		LMSA1~C Series LMSA1□~Z~3□~Z Series
LMAHSA-W	Digital	Bare cable		
LMAHF1	Digital	Connector		LMFA0~2 Series
LMAHF1-W	Digital	Bare cable		
LMAHF2	Digital	Connector		LMFA3~6 Series
LMAHF2-W	Digital	Bare cable		


Outlet mode and signal pin illustration


Example 1: Connector outlet mode and signal cable pin illustration



Signal cable	
Signal	Color
Vcc	1
Hall A(out)	2
Hall B(out)	3
Hall C(out)	4
GND	5
	Casing


Example 2: Bare cable outlet mode and signal cable pin illustration





Signal cable	
Signal	Color
Vcc	Brown
Hall A(out)	White
Hall B(out)	Gray
Hall C(out)	Yellow
GND	Green
	Isolation net

Note:

- (1). In the example 2, the signal cable pin not include the type of LMAHF2 and LMAHF2-W.
- (2). The signal cable pin of LMAHF2 and LMAHF2-W as follow.

Signal cable		
Signal	Color	Color
Vcc	Brown	1
Hall B(out)	White	2
Hall C(out)	Gray	3
Hall A(out)	Yellow	4
GND	Green	5
	Shield	Casing

Hall sensor specification	Output signal	Outlet mode	Hall sensor Illustration of dimensions	Applicable linear motor series
LMAH-EA-D-□□□-7-0	Digital	Connector		LME-A Series
LMAH-EA-D-□□□-0-0	Digital	Bare cable		
LMAH-EB-D-□□□-7-0	Digital	Connector		LME-B Series
LMAH-EB-D-□□□-0-0	Digital	Bare cable		

Note :

□□□ : Mean the length of the outlet line · Unit : m °






Outlet mode and signal pin illustration																																																	
<p>LME-A 、LME-B series : Connector outlet mode and signal cable pin illustration</p> <div><p>LME-A series</p></div> <div><p>LME-B series</p></div> <table><tr><th colspan="2">Signal cable</th></tr><tr><th>Signal</th><th>Connector</th></tr><tr><td>Vcc</td><td>1</td></tr><tr><td>Hall A (out)</td><td>2</td></tr><tr><td>Hall B (out)</td><td>3</td></tr><tr><td>Hall C (out)</td><td>4</td></tr><tr><td>GND</td><td>5</td></tr><tr><td>⏏</td><td>Casing</td></tr></table>	Signal cable		Signal	Connector	Vcc	1	Hall A (out)	2	Hall B (out)	3	Hall C (out)	4	GND	5	⏏	Casing	<p>LME-A series : Bare cable outlet mode and signal cable pin illustration</p> <div><table><tr><th colspan="2">Signal cable</th></tr><tr><th>Signal</th><th>Color</th></tr><tr><td>Vcc</td><td>Brown</td></tr><tr><td>Hall A (out)</td><td>Red</td></tr><tr><td>Hall B (out)</td><td>Gray</td></tr><tr><td>Hall C (out)</td><td>Yellow</td></tr><tr><td>GND</td><td>White</td></tr><tr><td>⏏</td><td>Isolation net</td></tr></table></div> <p>LME-B series : Bare cable outlet mode and signal cable pin illustration</p> <div><table><tr><th colspan="2">Signal cable</th></tr><tr><th>Signal</th><th>Color</th></tr><tr><td>Vcc</td><td>Brown</td></tr><tr><td>Hall A (out)</td><td>White</td></tr><tr><td>Hall B (out)</td><td>Gray</td></tr><tr><td>Hall C (out)</td><td>Yellow</td></tr><tr><td>GND</td><td>Green</td></tr><tr><td>⏏</td><td>Isolation net</td></tr></table></div>	Signal cable		Signal	Color	Vcc	Brown	Hall A (out)	Red	Hall B (out)	Gray	Hall C (out)	Yellow	GND	White	⏏	Isolation net	Signal cable		Signal	Color	Vcc	Brown	Hall A (out)	White	Hall B (out)	Gray	Hall C (out)	Yellow	GND	Green	⏏	Isolation net
Signal cable																																																	
Signal	Connector																																																
Vcc	1																																																
Hall A (out)	2																																																
Hall B (out)	3																																																
Hall C (out)	4																																																
GND	5																																																
⏏	Casing																																																
Signal cable																																																	
Signal	Color																																																
Vcc	Brown																																																
Hall A (out)	Red																																																
Hall B (out)	Gray																																																
Hall C (out)	Yellow																																																
GND	White																																																
⏏	Isolation net																																																
Signal cable																																																	
Signal	Color																																																
Vcc	Brown																																																
Hall A (out)	White																																																
Hall B (out)	Gray																																																
Hall C (out)	Yellow																																																
GND	Green																																																
⏏	Isolation net																																																

Table 3.3.3.1.2 Hall sensor specification comparison chart with Analog signal for iron core linear motors

































Hall sensor specification	Output signal	Outlet mode	Hall sensor Illustration of dimensions	Applicable linear motor series	Outlet mode and signal pin illustration																		
LMAHSA-D	Analog	Bare cable		LMS series	<p>Example: Analog output signal bare cable mode and signal cable pin illustration</p>     <table><tr><th colspan="2">Signal cable</th></tr><tr><th>Signal</th><th>Color</th></tr><tr><td>Vcc</td><td>Brown</td></tr><tr><td>A+</td><td>Red</td></tr><tr><td>A-</td><td>Blue</td></tr><tr><td>B+</td><td>Yellow</td></tr><tr><td>B-</td><td>Green</td></tr><tr><td>GND</td><td>White</td></tr><tr><td></td><td>Isolation net</td></tr></table>	Signal cable		Signal	Color	Vcc	Brown	A+	Red	A-	Blue	B+	Yellow	B-	Green	GND	White		Isolation net
Signal cable																							
Signal	Color																						
Vcc	Brown																						
A+	Red																						
A-	Blue																						
B+	Yellow																						
B-	Green																						
GND	White																						
	Isolation net																						
LMAHSAA-D	Analog	Bare cable		LMSA1~C Series LMSA1□-Z~3□-Z Series																			
LMAHFA1-D	Analog	Bare cable		LMFA0~2 series																			
LMAHFA2-D	Analog	Bare cable		LMFA3~6 series																			

Table 3.3.3.1.3 Hall sensor specification comparison chart with digital signal for LMC

Hall sensor specification	Output signal	Outlet mode	Hall sensor Illustration of dimensions	Applicable linear motor series	Outlet mode and signal pin illustration																
LMAHC	Digital	Connector		LMCA/LMCB/ LMCC series	<p>Example 1: Connector outlet mode and signal cable pin illustration</p> <div><div><p>Connector</p><p>D-Sub male 9 channel plug</p></div><div></div></div> <table><thead><tr><th colspan="2">Signal cable</th></tr><tr><th>Signal</th><th>Connector</th></tr></thead><tbody><tr><td>Vcc</td><td>1</td></tr><tr><td>Hall A(out)</td><td>2</td></tr><tr><td>Hall B(out)</td><td>3</td></tr><tr><td>Hall C(out)</td><td>4</td></tr><tr><td>GND</td><td>5</td></tr><tr><td></td><td>Casing</td></tr></tbody></table>	Signal cable		Signal	Connector	Vcc	1	Hall A(out)	2	Hall B(out)	3	Hall C(out)	4	GND	5		Casing
Signal cable																					
Signal	Connector																				
Vcc	1																				
Hall A(out)	2																				
Hall B(out)	3																				
Hall C(out)	4																				
GND	5																				
	Casing																				
LMAHC-W	Digital	Bare cable																			
LMAHC2	Digital	Connector		LMCD/LMCE series	<p>Example 2: Bare cable outlet mode and signal cable pin illustration</p> <div></div> <table><thead><tr><th colspan="2">Signal cable</th></tr><tr><th>Signal</th><th>Color</th></tr></thead><tbody><tr><td>Vcc</td><td>Brown</td></tr><tr><td>Hall A(out)</td><td>White</td></tr><tr><td>Hall B(out)</td><td>Gray</td></tr><tr><td>Hall C(out)</td><td>Yellow</td></tr><tr><td>GND</td><td>Green</td></tr><tr><td></td><td>Isolation net</td></tr></tbody></table>	Signal cable		Signal	Color	Vcc	Brown	Hall A(out)	White	Hall B(out)	Gray	Hall C(out)	Yellow	GND	Green		Isolation net
Signal cable																					
Signal	Color																				
Vcc	Brown																				
Hall A(out)	White																				
Hall B(out)	Gray																				
Hall C(out)	Yellow																				
GND	Green																				
	Isolation net																				
LMAHC2-W	Digital	Bare cable																			
LMAHC3	Digital	Connector		LMCF series	<p>Example: Bare cable outlet mode and signal cable pin illustration</p> <div></div> <table><thead><tr><th colspan="2">Signal cable</th></tr><tr><th>Signal</th><th>Color</th></tr></thead><tbody><tr><td>Vcc</td><td>Brown</td></tr><tr><td>Hall A(out)</td><td>White</td></tr><tr><td>Hall B(out)</td><td>Gray</td></tr><tr><td>Hall C(out)</td><td>Yellow</td></tr><tr><td>GND</td><td>Green</td></tr><tr><td></td><td>Isolation net</td></tr></tbody></table>	Signal cable		Signal	Color	Vcc	Brown	Hall A(out)	White	Hall B(out)	Gray	Hall C(out)	Yellow	GND	Green		Isolation net
Signal cable																					
Signal	Color																				
Vcc	Brown																				
Hall A(out)	White																				
Hall B(out)	Gray																				
Hall C(out)	Yellow																				
GND	Green																				
	Isolation net																				
LMAHC3-W	Digital	Bare cable																			
LMAHEF3-W	Digital	Bare cable		LMC-EFC/ LMC-EFE/ LMC-EFF series	<p>Example: Bare cable outlet mode and signal cable pin illustration</p> <div></div> <table><thead><tr><th colspan="2">Signal cable</th></tr><tr><th>Signal</th><th>Color</th></tr></thead><tbody><tr><td>Vcc</td><td>Brown</td></tr><tr><td>Hall A(out)</td><td>White</td></tr><tr><td>Hall B(out)</td><td>Gray</td></tr><tr><td>Hall C(out)</td><td>Yellow</td></tr><tr><td>GND</td><td>Green</td></tr><tr><td></td><td>Isolation net</td></tr></tbody></table>	Signal cable		Signal	Color	Vcc	Brown	Hall A(out)	White	Hall B(out)	Gray	Hall C(out)	Yellow	GND	Green		Isolation net
Signal cable																					
Signal	Color																				
Vcc	Brown																				
Hall A(out)	White																				
Hall B(out)	Gray																				
Hall C(out)	Yellow																				
GND	Green																				
	Isolation net																				

Note: LMAHEF3-W are not sold separately, and it is necessary to place orders together with the corresponding forcer series. This Hall sensor is shipped after it is fastened onto the forcer.

Table 3.3.3.1.4 Hall sensor specification comparison chart with Analog signal for LMC






















Hall sensor specification	Output signal	Outlet mode	Hall sensor Illustration of dimensions	Applicable linear motor series	Outlet mode and signal pin illustration																		
LMAHCA-D	Analog	Bare cable		LMCA/ LMCB/ LMCC series	<div>Example: Bare cable outlet mode and signal cable pin illustration</div> <div></div> <table><tr><th colspan="2">Signal cable</th></tr><tr><th>Signal</th><th>Color</th></tr><tr><td>Vcc</td><td>Brown</td></tr><tr><td>A+</td><td>Red</td></tr><tr><td>A-</td><td>Blue</td></tr><tr><td>B+</td><td>Yellow</td></tr><tr><td>B-</td><td>Green</td></tr><tr><td>GND</td><td>White</td></tr><tr><td></td><td>Isolation net</td></tr></table>	Signal cable		Signal	Color	Vcc	Brown	A+	Red	A-	Blue	B+	Yellow	B-	Green	GND	White		Isolation net
Signal cable																							
Signal	Color																						
Vcc	Brown																						
A+	Red																						
A-	Blue																						
B+	Yellow																						
B-	Green																						
GND	White																						
	Isolation net																						

Table 3.3.3.1.5 Hall sensor specification comparison chart with digital signal for LMT

Hall sensor specification	Output signal	Outlet mode	Hall sensor Illustration of dimensions	Applicable linear motor series	Outlet mode and signal pin illustration																
LMDHTA	Digital	Connector		LMTA Series	Example 1: Connector outlet mode and signal cable pin illustration Connector D-Sub male 9 channel plug   <table border="1"><thead><tr><th colspan="2">Signal cable</th></tr><tr><th>Signal</th><th>Connector</th></tr></thead><tbody><tr><td>Vcc</td><td>1</td></tr><tr><td>Hall A(out)</td><td>2</td></tr><tr><td>Hall B(out)</td><td>3</td></tr><tr><td>Hall C(out)</td><td>4</td></tr><tr><td>GND</td><td>5</td></tr><tr><td></td><td>Casing</td></tr></tbody></table>	Signal cable		Signal	Connector	Vcc	1	Hall A(out)	2	Hall B(out)	3	Hall C(out)	4	GND	5		Casing
Signal cable																					
Signal	Connector																				
Vcc	1																				
Hall A(out)	2																				
Hall B(out)	3																				
Hall C(out)	4																				
GND	5																				
	Casing																				
LMDHTA-W	Digital	Bare cable																			
LMDHTB	Digital	Connector		LMTB Series	Example 2: Bare cable outlet mode and signal cable pin illustration  <table border="1"><thead><tr><th colspan="2">Signal cable</th></tr><tr><th>Signal</th><th>Color</th></tr></thead><tbody><tr><td>Vcc</td><td>Brown</td></tr><tr><td>Hall A(out)</td><td>White</td></tr><tr><td>Hall B(out)</td><td>Gray</td></tr><tr><td>Hall C(out)</td><td>Yellow</td></tr><tr><td>GND</td><td>Green</td></tr><tr><td></td><td>Isolation net</td></tr></tbody></table>	Signal cable		Signal	Color	Vcc	Brown	Hall A(out)	White	Hall B(out)	Gray	Hall C(out)	Yellow	GND	Green		Isolation net
Signal cable																					
Signal	Color																				
Vcc	Brown																				
Hall A(out)	White																				
Hall B(out)	Gray																				
Hall C(out)	Yellow																				
GND	Green																				
	Isolation net																				
LMDHTB-W	Digital	Bare cable																			
LMDHTC	Digital	Connector		LMTC Series	Example 2: Bare cable outlet mode and signal cable pin illustration  <table border="1"><thead><tr><th colspan="2">Signal cable</th></tr><tr><th>Signal</th><th>Color</th></tr></thead><tbody><tr><td>Vcc</td><td>Brown</td></tr><tr><td>Hall A(out)</td><td>White</td></tr><tr><td>Hall B(out)</td><td>Gray</td></tr><tr><td>Hall C(out)</td><td>Yellow</td></tr><tr><td>GND</td><td>Green</td></tr><tr><td></td><td>Isolation net</td></tr></tbody></table>	Signal cable		Signal	Color	Vcc	Brown	Hall A(out)	White	Hall B(out)	Gray	Hall C(out)	Yellow	GND	Green		Isolation net
Signal cable																					
Signal	Color																				
Vcc	Brown																				
Hall A(out)	White																				
Hall B(out)	Gray																				
Hall C(out)	Yellow																				
GND	Green																				
	Isolation net																				
LMDHTC-W	Digital	Bare cable																			

3.3.3.2 Hall sensor installation instructions

DANGER

Attention to Hall sensor stroke!



- ◆ To evaluate the installation of the Hall sensor, it's necessary to confirm that the full stroke of the stator cannot be exceeded. If the stator is exceeded, an error alarm may occur in the drive control.

When a hall sensor is fastened onto a forcer, the bottom surface of the Hall sensor needs to be coplanar with datum plane A or shall not exceed datum plane A.

Refer to S1 in section 3.1.2.1 for the installation gap of LMSA/LMSA-Z series.

Refer to S2 in section 3.1.2.2 for the installation gap of LMFA/LMFP series.

Refer to S3 in section 3.1.2.2 for the installation gap of LMFA/LMFP precision water-cooling series.




Figure 3.3.3.2.1 Hall sensor installation illustration

Note:

Maximum bending radius of hall sensor cable for LME series:

Do not bend the signal cable when the outlet is smaller than 30 mm, and the minimum bending radius is 40 mm. The static limit radius of the signal cable is 25 mm.

3.3.3.3 Selection of Hall sensor screws

For Hall sensors of iron core linear motors, M3 screws shall be used. For hall sensors of ironless linear motors, there are variations according to the model number.

Table 3.3.3.3.1 Hall sensor screw selection chart

Screw specification	Applicable Hall sensor series
M2	LMAHEF3, LMAHEF3-W
M3	LMAHS, LMAHS-W, LMAHSA, LMAHSA-W LMAHF1, LMAHF1-W, LMAHF2, LMAHF2-W LMAHSA-D, LMAHSAA-D, LMAHFA1-D, LMAHFA2-D LMAHC, LMAHC-W, LMAHC2, LMAHC2-W LMAHC3, LMAHC3-W, LMAHCA-D, LMDHTA, LMDHTA-W LMAH-EA-D-□□□-7-0、LMAH-EA-D-□□□-0-0、LMAH-EB-D-□□□-7-0、 LMAH-EB-D-□□□-0-0
M4	LMDHTB, LMDHTB-W, LMDHTC, LMDHTC-W

3.3.3.4 Hall encoder

Analog hall encoder is used on the linear motor positioning platform. Apart from the incremental linear scale and magnetic scale available in the market, it provides customers with an additional option of encoder for selection. It only requires the installation of a hall sensor read head such that encoder position scale can be omitted, and it is able to achieve excellent positioning capability when operating with the existing stator parts of the linear motor.

■ Characteristics

- (1). Use in conjunction with iron core linear motor.
- (2). Replace linear scale, magnetic scale encoders.
- (3). Easy for assembly.
- (4). Suitable to applications with general precision requirements for point-to-point long stroke.
- (5). Excellent dust-resistant, oil-resistant and water-resistant.





Figure3.3.3.4.1 Actual images of Hall encoder

3.3.3.5 Hall encoder coding instructions

■ Product model number coding principle



■ Signal pin illustration

Table 3.3.3.5.1 Hall encoder signal pin chart

Function	Signal	Color
Power	+5V	Brown
	GND	White
Output signal	SIN+	Green
	SIN-	Yellow
	COS+	Blue
	COS-	Red

3.3.3.6 Hall encoder characteristic specification

Table 3.3.3.6.1 Hall encoder characteristic chart

	LMAESA	LMAEF1	LMAEF2
Power supply	5V±5%	5V±5%	5V±5%
Pole pair pitch	30mm	30mm	46mm
Resolution ⁽¹⁾	7.5μm	7.5μm	11.5μm
Repeatability ⁽¹⁾	±15μm	±15μm	±23μm
Accuracy ⁽¹⁾⁽²⁾	±45μm	±45μm	±69μm
Signal Output signal	SIN/COS 1Vp-p	SIN/COS 1Vp-p	SIN/COS 1Vp-p
Operating temperature (shall not freeze)	0~50°C	0~50°C	0~50°C
Storage temperature (shall not freeze)	-5~60°C	-5~60°C	-5~60°C

Note:

- (1). Operate with HIWIN driver, subdivision quantity of 4000.
- (2). Accuracy refers to the error after compensation (operate with HIWIN driver)
- (3). LMAESA can be shipped together with the SSA single-axis positioning platform, and the repeatability can reach ±5μm.

3.3.3.7 Hall encoder dimension




Figure 3.3.3.7.1 Hall encoder dimension illustration

Table 3.3.3.7.1 Hall encoder specification dimension chart

Dimension	LMAESA-A	LMAEF1-A	LMAEF2-A
a(mm)	50	50	50
b(mm)	5, Bending radius R=25	5, Bending radius R=25	5, Bending radius R=25
c(mm)	500~5000	500~5000	500~5000
d(mm)	3.9	4.4	4.4
e(mm)	5	5	5
f(mm)	10	10	10
g(mm)	20	20	20
h(mm)	2-Ø3.5 THRU, Ø6x3DP	2-Ø3.5 THRU, Ø6x3DP	2-Ø3.5 THRU, Ø6x3DP
j(mm)	23.1	26.6	26.6
k(mm)	13.1	16.6	15.6
m(mm)	24.3	24.3	24.3
n(mm)	72.3	72.3	98.5
gap(mm)	1.1	1.4(Cover type)/ 1.9(Epoxy type)	1.4(Cover type)/ 1.9(Epoxy type)


4. Installation

4. Installation	4-1
4.1 Mechanical installation	4-2
4.1.1 Iron core linear motor installation	4-2
4.1.1.1 Precautions for handling stator	4-2
4.1.1.2 Precautions for installation of forcer and stator	4-8
4.1.1.3 Precautions for installation of LMSC forcer and stator	4-14
4.1.2 Ironless linear motor installation	4-20
4.1.2.1 Precautions for installation of the LMC forcer and stator	4-20
4.1.2.2 Precautions for installation of LMT forcer and stator	4-25
4.1.3 Water-cooling linear motor cooling system installation	4-30
4.1.3.1 Forcer and stator precision water-cooling installation	4-30
4.1.3.2 Water-cooling motor quick connector installation	4-32
4.1.3.3 Precision water-cooling motor quick connector installation	4-33

4.1 Mechanical installation

4.1.1 Iron core linear motor installation

Stator unit warning label



4.1.1.1 Precautions for handling stator

WARNING

Risk of third-party components.



- ◆ No accept of warranty to use third-party components. It is not allowed to use or mix HIWIN products (Stator, forcer, ...) with third-party products. This may will cause problems and dangerous risk during assembly and axis movements.

WARNING

Risk of Stator access.

To avoid damage to products and harm to workers, take the stator in the correct way.



- ◆ The magnet warning label shall be attached at visible areas in order to prevent personnel injury.
- ◆ Please handle the stator with proper method in order to prevent personnel injury or stator damage.
- ◆ Please correctly take the stator to prevent personnel from injury or the stator from being damaged. (refer to figure 4.1.1.1.3).
- ◆ No matter what method is used, do not directly take the stator by handling the edge of the cover (refer to figure 4.1.1.1.4) Otherwise, personnel may get injured and the stator may be damaged.

WARNING

Risk of injury and material damage.



- ◆ Incorrect alignment of the stator segments can lead to malfunction and/or uncontrolled movement of the motor.
- ◆ Arrange the stator segments in the correct order. (refer to figure 4.1.1.1.5)

! WARNING

Risk of crushing from strong attraction forces.

The permanent magnets of the stators cause strong attraction and repulsion forces when the stator segments are connected in series.



- ◆ Do not remove stators from their packaging until directly before their installation.
- ◆ Never unpack several stators at the same time.
- ◆ Never place stators next to each other unsecured.
- ◆ Immediately mount unpacked stators.
- ◆ If the installation component with cable, must also pay attention to the risk of pinching.

! WARNING

Risk of death as a result of permanent magnet field.

Even when the motor is switched off, the permanent can put people with active medical implants at risk, who come close to the motors.



- ◆ Please be at least 50 mm away from the permanent magnets.
- ◆ People with heart rhythm devices or metal implants, maintain a minimum distance of 500 mm from the permanent magnets (trigger threshold for static magnetic fields of 0.5 mT as per directive 2013/35/EU).

! WARNING

Risk of damage as a result of permanent magnet field.

When working within a distance of 100 mm of components with permanent magnets, the magnetic field produces a strong magnetic attraction to magnetizable material.



- ◆ Do not underestimate the strength of magnetic attraction.
- ◆ In the induction zone, please do not carry the magnetizable material.
- ◆ Please use the tools that non-magnetized material.
- ◆ Please avoid the movement of the permanent magnet assembly relative to the conductive material, and the conductive material relative to the permanent magnet assembly.
- ◆ Only open the package of the motor assembly when it needs to be installed.
- ◆ When open the package, install components containing permanent magnets immediately.
- ◆ The installed Linear motor that needs to prevent accidental operation.

! CAUTION

Risk of working temperature.

Beware the operating environment of the stator to avoid damage.



- ◆ Max. allowable stator temperature is 70°C.

■ Packaging material description(Stator)


(1). Outer box.



(2). Open the outer box.



(3). Open the second layer of the outer box.



(4). Take out the inner box, and taking the stator. (Don't taking multiple stators in the same time.)





Figure4.1.1.1.1 Iron core stator packaging material

■ Packaging material description(Forcer)

(1). Outer box.



(2). Open the outer box.



(3). Open the second layer of the outer box.




(4). Take out the inner box, and taking the forcer.




Figure4.1.1.1.2 Iron core forcer packaging material

■ Correct




Lean the stator on one side of the workbench. Hold the stator by handling its base.



Lean the stator on one side with the non-magnetic auxiliary tool. Hold the stator by handling its base.

Figure 4.1.1.1.3 Correct method of handling the stator

■ Incorrect




Do not hold the stator by handling the edge of the cover.



To prevent personnel from injury or the stator from being damaged, taking the stator by contacting the edge of the cover is strictly prohibited.

Figure 4.1.1.1.4 Incorrect method of handling the stator

■ Correct assembly of stator



■ Incorrect assembly of stator




Figure 4.1.1.1.5 Correct and incorrect assembly of stator

4.1.1.2 Precautions for installation of forcer and stator

DANGER



Danger from strong magnet!

- ◆ There is strong magnetic attraction between forcer and stator. To avoid harm to workers, conform to the regulations.
- ◆ There is a powerful attraction force (several hundred kilogram of force) between the forcer and stator of LMSA/LMFA. Installation personnel are requested to follow the manual to perform the installation in order to prevent clamping injury by the forcer and stator.

WARNING



Risk of Linear Motor assembly.

To avoid harm to workers, install the forcer and stator according to the regulations.

- ◆ When a multiple set of forcers are installed in parallel, please be aware of the span specification and motor phase in order to ensure the effective thrust force.
- ◆ During the installation of the forcer, please be aware of the air gap between the forcer and the stator. If it is not installed properly, it may increase the cogging force or reduce the motor thrust force.
- ◆ Before installation of the forcer, it is normal as a gap exists when the forcer is placed on the platform, as shown in figure 4.1.1.2.4. To install the forcer assembly, fasten the screws from the center portion toward the two left and right ends sequentially, as shown in figure 4.1.1.2.5. After the fastening is complete, there is no air gap between the forcer and the forcer base, as shown in figure 4.1.1.2.6.
- ◆ Please be aware of the strong magnetic attraction force between the two stators. It is prohibited to place hands between the two stators (as shown in figure 4.1.1.2.9) in order to prevent personnel injury (magnetic objects and watches etc. shall also be kept away).
- ◆ During the installation of a multiple sets of stators, the stator length may have accumulated tolerance such that hole position deviation may occur. Such occurrences are normal. Consequently, during the installation, a spacer of 0.1~0.2 mm can be placed between two stators to assist the adjustment of the screw positioning (as shown in figure 4.1.1.2.10), and once the positioning is complete, then perform fastening. After fastening is complete, then remove the spacer.
- ◆ Do not lock the stator unilaterally, as there is a risk of warping, as shown in figure 4.1.1.2.11.
- ◆ To lock the stator holes, please follow the marked order to avoid the risk of deformation, as shown in figure 4.1.1.2.12.


! CAUTION

The risk of linear motors.



- ◆ For the screw torque strength for fastening the forcer and stator assembly, please refer to section 3.2.2.2.
- ◆ The maximum fastening depth of screws selected for the stator depends on the threaded holes of the customer's platform. For the minimum fastening depth, please refer to section 3.2.2.2.
- ◆ For the maximum fastening depth and the minimum fastening depth of screws selected for the forcer, please refer to section 3.2.2.2.

To transport a large forcer (such as LMFA/LMFP), it is necessary to use a lifting tool and ensure that it is completely opposite from each other at both ends in order to perform the transportation. If the forcer weight is >20kg, please use more than three ropes for lifting in order to prevent any danger.



Step to assemble :

■ First stator installation

First, install one set of the stator. During installation, please be aware of the level of parallelism of the sliding track and the stator, followed by using screws to ① install ② the stator on the platform ③. (refer to figure 4.1.1.2.1)

■ Forcer base and forcer installation

Use screws ④ to install the ⑤ forcer base onto the sliding block ⑥. (refer to figure 4.1.1.2.2)

Use screws to install ⑧ the forcer ⑦ onto the forcer base. The installation method shall be performed by fastening the screws from the center portion toward the two left and right ends sequentially. (refer to figure 4.1.1.2.3)

■ Stator installation

Move the forcer base ⑨ on top of the platform to facilitate the installation of other stator. (refer to figure 4.1.1.2.7)

Use screws to install ⑪ the stator ⑩ onto the platform, and slide to move the forcer base to ensure that there is no interference. (refer to figure 4.1.1.2.8)

When assembling, align the stator base plates to the same straight line. (refer to figure 4.1.1.1.5-Correct)

Avoid misalignment during stator assembly. (refer to figure 4.1.1.1.5-Incorrect)

When locking the stator locking bolts, please roughly tighten all the bolts in a pre-locking manner, and finally lock them with the required locking torque to avoid stator distortion caused by direct locking of a single bolt. (refer to figure 4.1.1.2.11 and figure 4.1.1.2.12)




Figure 4.1.1.2.1 First stator installation




Figure 4.1.1.2.2 Forcer base installation






Figure 4.1.1.2.3 Forcer installation



The front of the motor



The rear of the motor

Figure 4.1.1.2.4 Installation gap confirmation




Figure 4.1.1.2.5 Forcer installation sequence illustration




Figure 4.1.1.2.6 Forcer gap illustration




Figure 4.1.1.2.7 Forcer base movement




Figure 4.1.1.2.8 Stator installation




Figure 4.1.1.2.9 Please be aware of the strong magnetic attraction force between the stators in order to prevent clamping injury of personnel hands.




Figure 4.1.1.2.10 Recommended use of spacer to assist the positioning during fastening of a multiple set of stators.



Figure 4.1.1.2.11 Avoid skewing after tightening the unilateral screws

Please lock screw in the order of the marked numbers, as follow:

(1)→(2)→(3)→(4)→(5)→(6)→(7)
→(8)→(9)→(10)




Figure 4.1.1.2.12 Screw locking sequence

4.1.1.3 Precautions for installation of LMSC forcer and stator

WARNING

Risk of damage to the motor assembly.


Beware the structural strength of the designed equipment because there is strong magnetic attraction between forcer and stator. Insufficient structural strength will lead to structure deformation. Too much installation tolerance will affect the adjusting performance of the equipment.



- ◆ There is a strong magnetic attraction force between the forcer and stator, and one side of the attraction force is at least 2850N.
- ◆ The installation structural strength at the two sides of the stators shall be considered in order to prevent any structural deformation due to the strong attraction force.
- ◆ When the gap between the forcer and stator is above 4.5 mm, the attracting force is close to 0.
- ◆ The polarity labels at the two sides of the stator shall be opposite from each other.
- ◆ Any uneven air gap in the LMSC magnetic brake linear motor can affect the attraction force between the forcer and stator. (refer to Figure 4.1.1.3.13)


■ Step to assemble (stator) :

- (1). Clean all installation surfaces first.
- (2). Apply screw fixation gel onto all screws for fastening the stator. (refer to figure 4.1.1.3.1)
- (3). Use non-magnetic material for spacing on top of the stator.
- (4). Place the stator in position.
- (5). Use a non-magnetic tool (refer to figure 4.1.1.3.2) to install one side of the stators for half of the stroke.
- (6). Place the non-magnetic object between the installation surfaces of the stators at two sides. (refer to figure 4.1.1.3.3)
- (7). Use the non-magnetic tool to install the other side of the stators for half of the stroke. (refer to figure 4.1.1.3.4)



Apply screw fixation gel onto the screws.

Figure 4.1.1.3.1 Apply screw fixation gel



Non-magnetic tool

Figure 4.1.1.3.2 Use non-magnetic tool to install the stator





Figure 4.1.1.3.3 Place the non-magnetic object



Install the other side of the stators

Figure 4.1.1.3.4 Use non-magnetic tool to install the stator

■ Step to assemble (forcer) :

- (1). Install the forcer onto the forcer base first. (refer to figure 4.1.1.3.5)
- (2). Install the force base onto the base sliding block. (refer to figure 4.1.1.3.6)
- (3). Use thickness gauge to adjust the air gap (refer to figure 4.1.1.3.7) to $0.75^{+0.25}_{-0.15}$.




Figure 4.1.1.3.5 Forcer installation




Figure 4.1.1.3.6 Forcer base installation




Figure 4.1.1.3.7 Air gap illustration




Figure 4.1.1.3.8 LMSC air gap-attracting force relationship graph

Table 4.1.1.3.1 Air gap-attracting force relationship chart

Air gap (mm)	0	0.1	0.2	0.3	0.4	0.5	0.6	0.7	0.75
Single side attracting force Fa (N)	4601	4313	4042	3796	3556	3338	3134	2942	2850

■ Step to assemble (Remaining stator) :

- (1). Move the forcer base to install the remaining stators. (refer to figure 4.1.1.3.9)
- (2). Use the non-magnetic tool to install one side of the stators for half of the stroke. (refer to figure 4.1.1.3.10)
- (3). Place the non-magnetic object between the installation surfaces of the stators at two sides. (refer to figure 4.1.1.3.11)
- (4). Use the non-magnetic tool to install the other side of the stators for half of the stroke. (refer to figure 4.1.1.3.12)




Figure 4.1.1.3.9 Forcer base movement




Figure 4.1.1.3.10 Install one side of stators




Figure 4.1.1.3.11 Place the non-magnetic object




Figure 4.1.1.3.12 Install the other side of stators




Figure 4.1.1.3.13 LMSC force and stator installation illustration

Table 4.1.1.3.2 LMSC uneven air gap-attraction force correspondence chart

Air gap 1 (mm)	0	0.05	0.15	0.25	0.35	0.45	0.55	0.65	0.75
Air gap 2 (mm)	1.5	1.45	1.35	1.25	1.15	1.05	0.95	0.85	0.75
Attracting force F_a (N)	2838	2633	2230	1840	1461	1090	724	361	0

4.1.2 Ironless linear motor installation

4.1.2.1 Precautions for installation of the LMC forcer and stator

WARNING



Risk of forcer and stator assembly.

Prevent any hand clamping injury when you apply the products.

- ◆ Please handle the stator assembly carefully to prevent any hand clamping injury.

CAUTION



- ◆ The stator warning label shall face upward.
- ◆ After the installation of the stator assembly according to Section 3.1.3, please pay special attention to the gap between the stators.
- ◆ For the screw torque for fastening the forcer and stator assembly, please refer to Section 3.2.2.2.
- ◆ For the selection of the screw length and thread depth, please refer to Section 3.2.2.2.



■ Packaging material description(Stator)**(1). Outer box.****(2). Open the outer box.****(3). Open the second layer of the outer box.****(4). Take out the inner box, and taking the stator. (Don't taking multiple stators in the same time.)**


Figure4.1.2.1.1 Ironless stator packaging material

■ Packaging material description(Forcer)

(1). Outer box.



(2). Open the outer box.



(3). Open the second layer of the outer box.



(4). Take out the inner box, and taking the forcer.




Figure4.1.2.1.2 Ironless forcer packaging material

■ Step to assemble :

- (1). Use clean wiping cloth to dip with alcohol (95% industrial alcohol), and clean the installation interface.
(refer to Figure 4.1.2.1.3)
- (2). Use screws ① to attach the stator assembly ② at the right most side onto the baseplate ③.(refer to Figure 4.1.2.1.4)
- (3). Use screws ④ to install the forcer base ⑤ onto the linear sliding block ⑥. (refer to Figure 4.1.2.1.5)
- (4). Move the forcer base ⑦ to the left most side to facilitate the fastening of the forcer assembly ⑧.
(refer to Figure 4.1.2.1.6)
- (5). Move the forcer assembly ⑨ installed properly to the right side, and determine whether there is any interference in the forcer and stator assembly in order to be ready for the installation of the next set of stator. (refer to Figure 4.1.2.1.7)
- (6). Fasten the remaining stator assemblies ⑩ onto the baseplate ⑪. (refer to Figure 4.1.2.1.8)
- (7). After the installation is complete, move, and slide the forcer base to confirm that there is no interference. (refer to Figure 4.1.2.1.9)




Figure 4.1.2.1.3 Clean the installation interface




Figure 4.1.2.1.4 Stator installation




Figure 4.1.2.1.5 Forcer base installation




Figure 4.1.2.1.6 Move the forcer base




Figure 4.1.2.1.7 Forcer installation




Figure 4.1.2.1.8 Stator installation




Figure 4.1.2.1.9 Smoothness confirmation

4.1.2.2 Precautions for installation of LMT forcer and stator **WARNING**

Risk of forcer and stator assembly.

Prevent any hand clamping injury when you apply the products.

- ◆ Please handle the stator assembly carefully to prevent any hand clamping injury.

 **CAUTION**

Risk of forcer and stator assembly.

For stator and forcer installation, beware the abnormal gap between units.

- ◆ After the installation of the forcer assembly according to section 3.1.4, the concentricity shall not be greater than 0.2mm.
- ◆ After the installation of the stator assembly according to section 3.1.4, please pay special attention to the gap between the stators.
- ◆ For the screw torque for fastening the forcer and stator assembly, please refer to section 3.2.2.2.
- ◆ For the selection of the screw length and thread depth, please refer to section 3.2.2.2.

■ Packaging material description(Stator)

1. Outer box.



2. Open the outer box.



3. Take out the buffer material.



4. Taking the stator, don't taking multiple stators in the same time.




Figure4.1.2.2.1 tubular motor stator packaging material

■ Packaging material description(Forcer)

1. Outer box.



2. Open the outer box.



3. Open the second layer of the box.



4. Take out the inner box, and taking the forcer.



Figure4.1.2.2.2 tubular motor forcer packaging material

■ Step to assemble :

- (1). Use clean wiping cloth to dip with alcohol (95% industrial alcohol), and clean the stator assembly.
(refer to figure 4.1.2.2.3)
- (2). Place the forcer assembly ① onto the stator assembly ②. (refer to figure 4.1.2.2.4)
- (3). Use screws ③ to install the stator assembly ④ onto the fixation base ⑤, and measure the height difference and the left and right difference, and such difference shall not be greater than 0.2mm. (refer to figure 4.1.2.2.5)
- (4). Use screws ⑥ to install the forcer base ⑦ onto the sliding block ⑧. (refer to figure 4.1.2.2.6)
- (5). Use screws ⑨ to fasten the forcer assembly ⑩ onto the forcer base ⑪. (refer to figure 4.1.2.2.7)
- (6). After the installation is complete, move, and slide the forcer base to confirm that there is no interference. (refer to figure 4.1.2.2.8)




Figure 4.1.2.2.3 Clean the installation interface




Figure 4.1.2.2.4 Assemble the force and stator




Figure 4.1.2.2.5 Stator installation




Figure 4.1.2.2.6 Forcer base installation




Figure 4.1.2.2.7 Forcer installation




Figure 4.1.2.2.8 Smoothness confirmation

4.1.3 Water-cooling linear motor cooling system installation

4.1.3.1 Forcer and stator precision water-cooling installation

■ Step to assemble (Forcer precision water-cooling) : (refer to figure4.1.3.1.1 and figure4.1.3.1.2)

- (1). Place the forcer precision water-cooling ② on top of the forcer ③, and the hole positions of the two objects shall be aligned and the direction shall be consistent.
- (2). After aligning the hole positions of the forcer base ① and forcer precision water-cooling ② with the forcer ③, then perform installation.
- (3). After the fastening is complete, it can then be installed onto the working platform sliding block. Please refer to the instructions in section 4.1.1.2.




Figure 4.1.3.1.1 Forcer precision water-cooling installation illustration




Figure 4.1.3.1.2 Forcer precision water-cooling installation completion view

■ Step to assemble (Stator precision water-cooling) : (refer to figure 4.1.3.1.3 and figure 4.1.3.1.4)

- (1). Fasten the connecting base ① at one side onto the working position of the operating platform.
- (2). Insert the cooling pipes ② into the connecting base ① on the platform.
- (3). If the length of the stator ⑤ is longer, then use the joint method to connect the cooling pipes ②.
- (4). After all cooling pipes ② are installed completely, use the connecting base ⑥ at the other side for adjustment and fastening with the cooling pipes.
- (5). Place the stator ⑤ at the corresponding position on the cooling pipes ②.
- (6). Fasten all stators ⑤. For the fastening method of multiple sets of stators, please refer to the stator installation described in section 4.1.1.2.




Figure 4.1.3.1.3 Stator precision water-cooling installation illustration




Figure 4.1.3.1.4 Stator precision water-cooling installation completion view

4.1.3.2 Water-cooling motor quick connector installation

⚠ CAUTION



- ◆ When a quick connector of 1/8PT diameter is fastened onto the inlet or outlet, a white tape seal shall be wrapped around the connector in order to prevent any water leakage.
- ◆ When a quick connector of G1/8 diameter is fastened onto the inlet or outlet, with additional O-ring to prevent leakage.
- ◆ When a quick connector of PTFE coating on thread is fastened onto the inlet or outlet, a white tape seal is no need wrapped around the connector.
- ◆ The maximum pressure of the water-cooling loop is 10 bar.
- ◆ Use torque wrench (maximum torque shall not exceed 100 kgf-cm (9.8 Nm)).
- ◆ If the above is not installed properly, it may cause damage, water leakage, or rupture of the water-cooling connector.
- ◆ All of the accessories provided on the factory product shall not be removed arbitrarily; otherwise, the product performance is not guaranteed.

LMFA series of forcer specification includes LMFA and LMFP, and the pipe threads used are as shown in the table below:

Table 4.1.3.2.1 Forcer water-cooling connector threads

Forcer specification	Pipe thread
LMFA	1/8 PT
LMFP	G 1/8
LMSC	1/8PT

Water-cooling connector ⑫ refers to the inlet, and water-cooling connector ⑬ refers to the outlet.




Figure 4.1.3.2.1 Water-cooling connector installation location

4.1.3.3 Precision water-cooling motor quick connector installation

Water-cooling connector ⑫ refers to the inlet, and water-cooling connector ⑬ refers to the outlet, and both are G1/8.




Figure 4.1.3.3.1 Forcer precision water-cooling connector installation location




Figure 4.1.3.3.2 Stator precision water-cooling connector installation location(This page is intentionally left blank.)

(This page is intentionally left blank.)

5. Troubleshooting

5.	Troubleshooting	5-1
5.1	Troubleshooting	5-2

5.1 Troubleshooting

Table 5.1.1 Troubleshooting

Symptom	Cause	Action
Motor cannot rotate at all.	Wrong cable wiring	Check the cable connected to the controller.
Wrong rotating direction	Wrong encoder setting	Check encoder settings.
	Wrong motor power cable wiring	Interchange the two-phase power cable connected to the controller.
Smell of burning	Abnormal operation of cooling system	Check the cooling system.
	Wrong controller setting	Check controller settings.
	Wrong motor parameters setting	Check motor parameters setting.
Abnormal temperature of motor outer casing	Abnormal operation of cooling system	Check the cooling system.
	Wrong controller setting	Check controller settings.
	Abnormal operation	Check assembly method.
	Abnormal temperature control display	Check assembly method and grounding of shielding.
Unstable rotation (vibration)	Insulation failure	Check the resistance value of phase/earth is larger than 10MΩ.
	Wrong encoder installation	Check installation stiffness of encoder.
	Wrong encoder signal	Check encoder grounding and connection.
	Encoder signal interference	Check grounding of shielding.
	Wrong controller setting	Check controller settings.
Hard to rotate or abnormal friction noise	Abnormal installation of rotor	Check assembly method.
	Foreign objects exist in the air gap.	Remove foreign objects.
	Abnormal air gap	Check assembly tolerance and structural rigidity.

6. Maintenance and Waste Disposal



- 6. [Maintenance and Waste Disposal](#)..... 6-1
 - 6.1 [Waste disposal](#)..... 6-2

6.1 Waste disposal

DANGER



Danger from strong magnet!

- ◆ Permanent magnetic materials must be fully demagnetized before subsequent treatment is performed. Otherwise, it may cause serious damage.

CAUTION



Danger caused by environmentally hazardous substances!

- ◆ Waste disposal must follow the local relevant regulations and the recycling procedure of recyclable materials.
- ◆ Waste materials include electronic materials, iron, aluminum, insulating materials, permanent magnetic materials, etc. Please follow the relevant procedures for recycling.
- ◆ As for the demagnetization of permanent magnetic materials, if they are put in the furnace in a solid, heat-resistant container made of non-magnetic material, the heat must be at least 300°C during a holding time of at least 30 minutes.
- ◆ If the packaging materials used in the product are recyclable, they must be recycled.

When products relevant to linear motor reach usage expiration, they need to be treated properly before disposal, especially the permanent magnetic materials. If they are not demagnetized according to the warning aforementioned, they might cause severe injury to workers.

HIWIN is not responsible for any damages, accidents, or injuries caused by failure to follow the above precautions.

7. Appendix



- 7. [Appendix](#) 7-1
 - [7.1 Glossary](#) 7-2
 - [7.2 Unit conversion](#) 7-6
 - [7.3 Customer request form](#) 7-8

7.1 Glossary

- Continuous force F_c [N]
It is defined as the output thrust force of the motor running continuously without stopping under the environmental temperature of 25°C, and such Continuous force corresponds to the continuous current applied to the motor I_c .
- Continuous current I_c [A_{rms}]
It is defined as the current that can be supplied to the motor coil continuously under the environmental temperature of 25°C, and it also generates the current for the Continuous force.
- Water-cooling Continuous force ($F_c(wc)$) [N]
It is defined as the output thrust force of the motor running continuously without stopping under the water-cooling temperature of 20°C, and such water-cooling Continuous force corresponds to the Continuous current(wc) applied to the motor I_c .
- Continuous current(wc) $I_c(wc)$ [A_{rms}]
It is defined as the current that can be supplied to the motor coil continuously under the water-cooling temperature of 20°C, and it also generates the current for the water-cooling Continuous force.
- Peak force F_p [N]
It is defined as the maximum thrust force that can be outputted by the motor within the time not exceeding one second. It is generally used for the purpose of acceleration and deceleration.
- Peak current I_p [A_{rms}]
It is defined as the instant large current corresponding to the peak thrust achieved by the motor, and for the normal scope of operation, the peak current is permitted for 1 second.
- Ultimate force F_u [N]
It is defined as the ultimate current I_u corresponding to the ultimate thrust. In the normal operating range, the ultimate current can be supplied for 0.5 seconds
- Ultimate force F_u [N]
It is defined as the output thrust force corresponding to the Ultimate current I_u of the motor.
- Ultimate current I_u [A_{rms}]
It is defined as five times of the continuous current I_c of the motor; under such current, the thrust force outputted by the motor is within the saturated non-linear zone, and the Force constant decreases. Input of such current can cause over-temperature risk of the motor, and the operating time is recommended to be less than 0.5 second.
- Attraction force F_a [N]
It is defined as the acting force between the forcer and stator of an iron core linear motor under the rated air gap, and the preload applied by such force on the sliding block is borne by the sliding track.

■ Maximum winding temperature T_{max} [°C]

It is defined as the acceptable maximum temperature of the motor coil. The actual equilibrium temperature of the motor depends on the factors of the mechanism, cooling method and the movement planning etc. There may be some deviation from the theoretical calculation, and the result of actual measurement is typically used.

■ Electrical time constant K_e [ms]

It is defined as the time required for the current supplied to the motor to reach 63% of the target value, and when such value is smaller, it means that the response time is faster.

■ Force constant K_f [N/A_{rms}]

It is defined as the output thrust force of the motor under the unit current, and except for the LMFA water-cooling motor series, when the rest of the series are under the normal operating scope, the output thrust force and the input current approach the linear relationship, and the non-linear portion is affected by the iron core saturation.




Figure 7.1.1

■ Resistance R_{25} [Ω]

It is defined as the line-to-line resistance of the motor measured when the coil temperature is 25°C; the resistance increases along with the increase of the temperature.

$$R_c = R_{25} \times (1 + 0.00393) \times (T_c - 25)$$

R_c : refers to the line-to-line resistance under any temperature

T_c : any temperature

■ Inductance L [mH]

It is defined as the line-to-line inductance (excluding stator) of the motor measured.

■ Pole pair pitch 2τ [mm]

It is defined as the distance between two magnets of the same polarity on the stator, i.e. N→N or S→S.




Figure 7.1.2

- **Back EMF constant K_v [$V_{rms}/(m/s)$]**
It is defined as the induced EMF generated by the unit speed of the motor when the magnet temperature is 25°C . It occurs when the coil senses a magnetic field change, and the EMF generated to resist the current passing through.
- **Motor constant K_m [$\text{N}/\sqrt{\text{W}}$]**
It is defined as the ratio of the motor output thrust force to the square root of the power consumption when the coil and magnet temperatures are 25°C . As the motor constant is higher, it means that when the motor outputs a specific thrust force, there is a lower power loss, and such constant is used as one of the indicators for determining the motor efficiency.
- **Thermal resistance R_{TH} [$^{\circ}\text{C}/\text{W}$]**
It is defined as the thermal resistance from the internal of the motor coil to the heat dissipating environment. As the thermal resistance is smaller, it means that under the same amount of heat input, the temperature difference between the coil and the heat dissipating environment is smaller, i.e. the heat dissipating effect is better.
- **Thermal time constant t_{TH} [sec]**
It is defined as the time required for the coil initial temperature to T_0 rise to 63% of the Maximum winding temperature T_{max} when the motor is supplied with the continuous current.




Figure 7.1.3

- **Minimum flow rate (L/min)**
It is defined as the minimum flow rate of the coolant required for the motor to reach the water-cooling Continuous force under the rated Temperature of cooling water $F_c(wc)$.
- **Temperature of cooling water [$^{\circ}\text{C}$]**
It is defined as the temperature required to be reached by the motor coolant under the minimum flow rate in order to achieve the water-cooling Continuous force $F_c(wc)$.
- **Pressure drop ΔP [bar]**
It is defined as the pressure difference between the inlet and outlet when the coolant is under the minimum flow rate.

- Peak force maximum speed V_{max,F_p} [m/s]
It is defined as the maximum speed that can be achieved by the motor under the Peak force; this parameter depends on the Maximum DC bus voltage.
- Maximum electric power input $P_{EL,max}$ [W]
It is defined as the required input power under the condition where the motor is operating at the Peak force with maximum speed V_{max,F_p} and Maximum dissipated heat output $Q_{P,H,max}$.
- Maximum dissipated heat output $Q_{P,H,max}$ [W]
It is defined as the heat generated by the coil of the motor when the coil is at the maximum temperature T_{max} .
- Stall current I_0 [A_{rms}]
It is defined as the current upper limit that can be supplied under the condition where the motor is under the environmental temperature of 25°C and the locked-rotor condition, and such value is related to the criteria of heat dissipation.
- Stall force F_0 [N]
It is defined as the thrust force upper limit that can be provided when the motor is under the short stroke (stroke smaller than the pole pair pitch 2τ) and the locked-rotor application, and such value is limited by the Stall current.
- Maximum DC bus voltage [V_{DC}]
It is defined as the Maximum DC bus voltage that can be used by the motor under the normal working environment.

7.2 Unit conversion

To convert the unit in column B to the unit in column A, multiply by the corresponding figure in the table.

■ Mass

Table 7.2.1

		B			
		g	kg	lb	oz
A	g	1	0.001	0.0022	0.03527
	kg	1000	1	2.205	35.273
	lb	453.59	0.45359	1	16
	oz	28.35	0.02835	0.0625	1

■ Linear velocity

Table 7.2.2

		B				
		m/s	cm/s	mm/s	ft/s	in/s
A	m/s	1	100	1000	3.281	39.37
	cm/s	0.01	1	10	3.281×10^{-2}	0.3937
	mm/s	0.001	0.1	1	3.281×10^{-3}	3.937×10^{-2}
	ft/s	0.3048	30.48	304.8	1	12
	in/s	0.0254	2.54	25.4	8.333×10^{-2}	1

■ Force

Table 7.2.3

		B		
		N	lb	oz
A	N	1	0.2248	3.5969
	lb	4.4482	1	16
	oz	0.2780	0.0625	1

■ Length

Table 7.2.4

		B				
		m	cm	mm	ft	in
A	m	1	100	1000	3.281	39.37
	cm	0.01	1	10	3.281×10^{-2}	0.3937
	mm	0.001	0.1	1	3.281×10^{-3}	3.937×10^{-2}
	ft	0.3048	30.48	304.8	1	12
	in	0.0254	2.54	25.4	8.333×10^{-2}	1












■ Temperature

Table 7.2.5

		B	
		°C	°F
A	°C	1	$(^{\circ}\text{F} - 32) \times 5 / 9$
	°F	$(^{\circ}\text{C} \times 9 / 5) + 32$	1

7.3 Customer request form

Table 7.3.1

Fields marked with asterisk (*) are required.				Date: _____	
Customer name: _____			Contact HIWIN:		
Email : _____			Job description:		
Tel: _____ Fax: _____			Business owners:		
*Industry/Application	_____		Multi-forcers	<input type="checkbox"/> Yes, quantity: _____ pcs <input type="checkbox"/> No	
*Operational environment	<input type="checkbox"/> Indoor, general 25℃ <input type="checkbox"/> Cleaning room, class: _____ <input type="checkbox"/> Vacuum, class: _____ <input type="checkbox"/> Others: _____		*Movement	<input type="checkbox"/> Point to point movement <input type="checkbox"/> Scanning	
*Stage type	<input type="checkbox"/> Single <input type="checkbox"/> XY axis <input type="checkbox"/> Dual axis Bridge <input type="checkbox"/> Gantry(single-driven) <input type="checkbox"/> Gantry(dual-driven) <input type="checkbox"/> Others: _____		Safety requirements	<input type="checkbox"/> CE <input type="checkbox"/> UL <input type="checkbox"/> Other _____	
*Payload	<input type="checkbox"/> Mass: _____ kg		Travel time	_____ sec	
External force (N)	X-axis _____ Y-axis _____ Z-axis _____ _____		Dwelling time	_____ sec	
*Max. speed (m/s)	X-axis _____ Y-axis _____ Z-axis _____ _____		Drive	Voltage	<input type="checkbox"/> 110V <input type="checkbox"/> 220V <input type="checkbox"/> Other: _____ V
*Max. acceleration (m/s ²)	X-axis _____ Y-axis _____ Z-axis _____ _____		Hall sensor	<input type="checkbox"/> Yes <input type="checkbox"/> Digital signal <input type="checkbox"/> Analog signal <input type="checkbox"/> No	
*Stroke (m)	X-axis _____ Y-axis _____ Z-axis _____ _____		The type of forcer power cable, the standard is cable (as shown in the figure below)		
*Stage installation	<input type="checkbox"/> Horizon Axis: _____ 		<input type="checkbox"/> Cable Applies to all types. 		
	<input type="checkbox"/> Vertical Axis: _____ 		<input type="checkbox"/> 90° connector Applies types: LMFx, LMTE 		
	<input type="checkbox"/> Hang Axis: _____ 		<input type="checkbox"/> Cable + round connector Applies types: LMFx LMC, LMT 		
	<input type="checkbox"/> Upside-down Axis: _____ 		<input type="checkbox"/> Cable + D-sub Applies types: LMSA, LMC-EFE, LMC-EFF, LMCF 		
Motion profile:			<input type="checkbox"/> External thread 		
			<input type="checkbox"/> Cable + Metal connector Applies types: LMFA, LMFP 		

The information below is to be filled out by HIWIN or authorized agents.
Recommended specification: